

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 22-Mar-23

Estimate no.

1234

Plate No. FBM3382K

Model. HONDA CB400X

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	REAR FENDER CRA	\$ 280.00	170	
2	REAR NUMBER PLATE CRA	\$ 2030.00	-	
3	REAR SIGNAL LIGHT LEFT SCRA	\$ 180.00	100	
4	REAR SIGNAL LIGHT RIGHT SCRA	\$ 180.00	100	
5	EXHAUST PIPE SCRA	\$ 950.00		
6	EXHAUST COVER SCRA	\$ 280.00	150	
7	REAR PILLION BAR LEFT SCRA	\$ 220.00	200	
8	REAR PILLION BAR RIGHT SCRA	\$ 220.00		
9	BODY UNDER COVER RIGHT SCRA	\$ 200.00	80	
10	CRASH BAR SCRA	\$ 450.00	380	
11	HANDLE BAR Dnt	\$ 380.00	120	
12	HANDLE BALANCER SCRA	\$ 150.00	-	
13	MIRROR RIGHT SCRA	\$ 150.00	95	
14	BRAKE LEVER RIGHT SCRA	\$ 120.00	65	
15	FRONT FAIRING COVER RIGHT SCRA	\$ 400.00	80	
16	MIRROR LEFT X NN	\$ 150.00		
17	CLUTH LEVER X NN	\$ 120.00		
18	LABOUR 250	\$ 500.00	250	
19	spray cover set	\$ 450	200	

PT = 1710

100 = 171

T = 1989

200 = 397.80

= 1591.20

≈ 1600

4 days L/S

24/3/23 1st time
3.30 pm

Sub Total : \$ 4,960.00
GST 8% \$ 357.12
Total: \$ 4,821.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.