

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/CT/23003093/4P3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW8543X

at Workshop m/s PP

of _____

Insured: G B J 9421H

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 834k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 174818088

Date / Time

Action / Instruction

Headling H10

Rep 10k

6/4/23 1/5 # 6500 in hand Alan

Veh No: SKW8543X Yr Regn: 18/11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A/

Make: mazda 3 sp ope c.c. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Reading: 37804 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BM7A 8G0323902

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/03/23 D.O.I. 24/3/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rrt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation:

____ S + RS, ____ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Allowed
24/3/23
1/5 # 6500
5 days

VEHICLE No: SKW 8543X

1PC	FRONT BUMPER	Dis/To.1	1083.20	\$1,250.00	—
2PCS	FRONT BUMPER SIDE RETAINERS @\$65.00	121		\$130.00	—
2PCS	FRONT BUMPER FOG LAMPS @\$305.00	11		\$610.00	X
2PCS	FRONT BUMPER FOG LAMP GARNISHS @\$160.00	11		\$320.00	X
2PCS	FRONT BUMPER LAMPS @\$320.00	11		\$640.00	X
1PC	FRONT BUMPER REINFORCEMENT	Surf	445.00	\$665.00	—
1PC	FRONT BUMPER REINFORCEMENT PROTECTOR	11		\$182.10	X
1PC	FRONT BUMPER INNER LOWER BRACKET	11		\$122.00	X
2PCS	FRONT BUMPER INNER BRACKETS @\$105.00	N/S crn		\$210.00	1PC
1SET	FRONT BUMPER CLIPS	121		\$50.00	—
1PC	FRONT BUMPER TOP	Dis	371	\$221.00	—
2PCS	FRONT BUMPER LOWER COVERS \$15.00	11		\$30.00	X
2PCS	FRONT FENDERS @\$545.00	N/S Surf 0/5 11	395.20	\$1,090.00	1PC
2PCS	FRONT FENDER INNER SHIELDS @\$165.00	11		\$330.00	X
1SET	FRONT FENDER INNER SHIELD CLIPS	11		\$50.00	X
1PC	HEADLAMP N/S H/D	Crn	2978.00	\$5,360.00	—
1PC	HEADLAMP WASHER UNIT N/S	N/S		\$490.00	X
1PC	FRONT SUPPORT PANEL	Crn	480	\$541.00	—
1PC	WIPER WASHER TANK	11		\$281.00	X
1PC	BONNET	0/5 Surf	1148	\$1,222.00	—
1PC	BONNET INNER RUBBER	121		\$45.00	—
1PC	BONNET LOCK	11		\$195.00	X
1PC	FRONT GRILLE	Crn		\$688.00	—
1PC	FRONT GRILLE OUTER CHROME	Crn		\$253.00	—
1PC	FRONT GRILLE INNER	Crn		\$331.20	—
				\$15,306.30	
	S.NETT				
1PC	FRONT LICENCE PLATE [OPC]	121		\$50.00	40
1PC	FRONT LICENCE PLATE SEAL & NUT	121		\$40.00	20
1PC	BONNET SEALANT	11		\$50.00	X
	TO CHECK WIRING			\$50.00	20
	TO APPLY WEEKEND SEAL			\$120.00	50
	TO CONDUCT WHEEL ALIGNMENT	11		\$120.00	X
	TO RESET & REPROGRAMME SYSTEM	11		\$450.00	X
	TO REFILL AIR CON GAS			\$120.00	100
	TO SPRAY RUST PROOFING			\$120.00	50
	LABOUR FOR PANEL BEATING & REPLACED PARTS			\$1,000.00	600

212/

TO PUTTY & SPRAY PAINTING

TOTAL \$1,500.00 800
\$18,926.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-8134-4
202
6207-52
60
1620
4181-52
6820