

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 23.30495 Date: 08th May 2023

Our Ref: CS3/ASM22004321/Rqp3e2-1

M/s HSBC Life (Singapore) Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJL 3286R INSURED VEHICLE: SJU 9085S ACCIDENT DATE: 07/05/2022

We thank you for your instruction on 24/03/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJL 3286R from M/s Auto Performance Appraisal.
- b) Singapore Accident Statement of Vehicles SJL 3286R, SJU 9085S and SCY 8288S.
- c) Police report of Vehicles SJL 3286R and SCY 8288S.
- d) Final Repair Bill of SJL 3286R from M/s Guan Auto Service.
- e) Colour damaged vehicle photographs of SJL 3286R.

Pre-Repair Inspection Date: 17/05/2022 at M/s Blk 7 Sin Ming Ind Est Sector C #01-82, Singapore 575642, Repairer: Guan Auto Service.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJL 3286R

Make & Model : Mitsubishi Lancer 1.6 A

Year of Registration : 2008

Chassis Number : JMYSTCS3A8U010555

Engine Capacity : 1584 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.