

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM22004321/Rqp3-1						
	AXA INSURANCE	PTE LTD		Ref:	C <del>OS/ASM22004321/y</del> 3	
	8 SHENTON WAY AXA TOWERSING			Date:	<del>10/05/2022</del> 24/03/2023	
				Code:	ASM	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SJU 9085S	Veh. Inspected	i	SJL 3286R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M040F1	Excess (\$)		0.00	
	Assign From H	ENG XINYI (SEAH ONG)	Assign Date		0 <del>3/05/2022</del> 24/03/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	07/05/2022	Inspection Dat	e		
	Survey held at	BLK 7 SIN MING IND EST SEC	SIN MING IND EST SECTOR C #01-82 S575642			
	Repairer	GUAN AUTO SERVICE				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					