

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

LUCKY JOINT CONSTRUCTION PTE LTD

17 TUAS AVE 3

SINGAPORE 639414

TAX INVOICE

Repair Code : CLM15837

Date in : 22/03/2023

Vehicle Num. : GBF6789M

Model : KIA K2500 6M/T

Chassis/Eng# : KNCSJX76LF7907535/D4CBE571248

Contact : 63676789 91706789, 86488294

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR END PANEL <i>Dented</i>	1	385.70	✓ 385.70
REAR NUMBER PLATE BRACKET HOLDER <i>Best</i>	1	125.30	✓ 125.30
REAR NUMBER PLATE LAMP <i>and</i>	1	168.00	✓ 168.00
REAR SPARE TYRE CARRIAGE <i>new</i>	1	469.70	✓ 469.70
REAR TAILGATE <i>Dented</i>	1	1268.70	✓ 1,268.70
REAR TAILGATE HINGES <i>new</i>	3	132.40	✓ 397.20
REAR TAILGATE SIDE LOCK L/R <i>LH Dented</i>	2	98.70	<i>2686.50</i> 98.70 ✓ 197.40
REAR TAILLAMP L/R <i>could</i>	2	195.70	✓ 391.40
REAR TAILLAMP PANEL L/R <i>RH Dented</i>	2	258.70	<i>2426.85</i> 258.70 ✓ 517.40
REAR TAILLAMP PANEL RUBBER STOPPER L/R <i>new</i>	4	10.50	✓ 42.00
Subtotal before discount			3,962.80
Percentage discount 10%			396.28
Sub-total 1			3,566.52
REAR NUMBER PLATE <i>Best</i>	1	25.00	✓ 25.00
REAR NUMBER PLATE FRAME <i>delnd</i>	1	50.00	<i>30</i> ✓ 50.00
REAR REVERSE SENSOR - SET <i>Dented</i>	1	280.00	<i>2w</i> 280.00
REAR STEP PANEL <i>Best</i>	1	250.00	<i>2w</i> 250.00
REAR TAILGATE '70KM' STICKER <i>new</i>	1	25.00	<i>15</i> 25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LUCKY JOINT CONSTRUCTION PTE LTD
17 TUAS AVE 3
SINGAPORE 639414

Contact : 63676789 91706789, 86488294

TAX INVOICE

Repair Code : CLM15837
Date in : 22/03/2023
Vehicle Num. : GBF6789M
Model : KIA K2500 6M/T
Chassis/Eng# : KNCSJX76LF7907535/D4CBE571248

REAR TAILGATE '7PAX' STICKER	<i>nu</i>	<i>665</i>	1	25.00	<i>15</i>	25.00
REAR TAILGATE 'DECAL' STICKER	<i>nu</i>		1	250.00	<i>180</i>	250.00
Subtotal before discount						905.00
Percentage discount 0%						0.00
Sub-total 2						905.00
Parts-total						4,471.52

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	1,940.00
Parts & Labour Total	6,411.52

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin
1/s 08/04/23.
05 Days
total: 4321.85
4/s: 3450 ✓