



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 5079A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	LH HEADLIGHT ASSY (SN)	CRACKED	696.00	696.00
1	RH HEADLIGHT ASSY (SN)	CRACKED	663.00	663.00
1	LH FRONT FENDER (SN)	TO REPAIR SEE LABOUR	1,172.00	-
1	RH FRONT FENDER (SN)	TO REPAIR SEE LABOUR	1,172.00	-
1	FRONT BUMPER (SN)	DEFORMED / TORN	1,281.00	1,281.00
1	FRONT BUMPER BRACKET SUPPORT (SN)	NECESSARY	88.00	88.00
1	UPR STONE GUARD GRILLE (SN)	TORN	366.00	366.00
1	LWR STONE GUARD GRILLE (SN)	TORN	519.00	519.00
1	TOW COVER (SN)	TWISTED	76.00	76.00
1	FRONT FOG LAMP MOULDING (SN)	GRAZED	253.00	253.00
1	INNER FRONT BUMPER FRAME (SN)	TORN	448.00	448.00
1	LH AIR COOL PARTITION (SN)	TORN	114.00	114.00
1	RH AIR COOL PARTITION (SN)	TORN	114.00	114.00
1	BRAND BADGE CHROME (SN) (ADDITIONAL)	SCRATCHED / CRACKED	341.00	341.00
			7,353.00	4,979.00
	<u>LABOUR</u>			
	TO REPLACE LH & RH HEADLAMP, LH & RH FENDER PANEL, FRONT BUMPER, BUMPER BRACKET SUPPORT, UPR & LWR STONE GUARD, TOW COVER, FOG LAMP MLDG, INNER FRT BUMPER FRAME, LH & RH AIR COOL PARTITION. STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF LH FRONT FENDER AND RH FRONT FENDER.		3,040.00	2,280.00
	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS (FRONT BUMPER, LHF & RHF FENDER).		2,200.00	1,650.00
	TO CARRY OUT DIAGNOSTIC CHECK ON DIAGNOSTIC TOOLS & CLEAR TROUBLE CODE.		380.00	380.00
	TO CHECK WIRING & ELECTRICAL SYSTEM.		100.00	80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-CORROSION ON AFFECTED AREAS.	NOT NECESSARY	50.00	-
			5,770.00	4,390.00
GRAND TOTAL			13,123.00	9,369.00
RECOMMENDED COST OF REPAIRS				9,369.00
LESS EXCESS				-600.00
NETT LIABILITY				8,769.00

Report Ref No. CS/FCI23003096/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.