



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222

F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S	LONPAC INSURANCE BHD
	300 BEACH ROAD, #17-04/06 The Concourse, SINGAPORE 199555
Insured	YEOH BROTHERS TRANSPORT PTE LTD
Policy	5129281504-000042

ESTIMATE BILL

GST Reg. No: 199800107D

Date: 24/3/2023

Our Case Ref.

Accident Date 8/3/2023

Damaged Vehicle No: PC927X

S/no	Description	QTY	Price	Remark
	<u>Replaced Parts</u>			
1	SIDE PANEL RH	1 PC	\$3,960.50	
2	SEALANT	8 PC	\$ 392.00	
3	ARTWORK		\$1,000.00	
	<u>Labour Charges</u>			
1	LABOUR TO REMOVE, REINSTALL AND CHECK WIRE HARNESS		\$ 500.00	
2	LABOUR TO REMOVE, AND REINSTALL PASSANGER SEAT.		\$1,280.00	
3	LABOUR TO REMOVE, REPLACE AND REINSTALL SIDE PANEL RH.		\$3,840.00	
4	LABOUR TO RESPRAY SIDE PANEL		\$1,920.00	
TOTAL			\$ 12,892.50	