

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/H5B23003099/4293**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC4433Mat Workshop m/s Speedlinkof SH/B9838e

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 8100k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1025

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 44871Veh No: SMC4433M Yr Regn: 29/06/18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA / ComfortlineMake: Volkswagen Tiguan c.c 1395Colour: white A/C: Insured / Std / NI / NASp. Reading: 68391 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG2225N2JW849980Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: _____
R: 235/55R218

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or nexenFront 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 16/03/23 D.O.I. 24/3/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRee o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 16k.27/3/23 H5 44800 informed hunt

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 , #01-73 , AUTOBAY , SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

not Allowed
date
24/3/23
1/6 H 4800
4 days

VEHICLE NUMBER: SMC4433M

MAKE & MODEL: VOLKSWAGEN TIGUAN COMFORTLINE

DOA: 16.03.2023

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAIL GATE	1	\$2,025.00	2 X
TAIL GATE LOGO	1	\$136.50	11 X
TAIL GATE LAMP @ 452.00	2	\$904.00	11 X
TAIL GATE BOARD	1	\$312.00	11 X
REAR NUMBER PLATE LIGHT @ 98.00	2	\$196.00	11 X
TAIL GATE INNER LOCK	1	\$1,170.00	11 X
REAR BUMPER	1	\$1,422.00	Dis
REAR BUMPER DIFFUSER	1	\$487.00	Dis
REAR BUMPER SIDE RETAINER @ 147.90	2	MSM \$295.80	0/5 cm pc
REAR BUMPER REINFORCEMENT	1	418 \$650.00	BN
REAR BUMPER DIFFUSER LOWER COVER <i>rowing</i>	1	48 \$75.20	TPC
REAR BUMPER REFLECTOR @ 85.00	2	MSM \$170.00	0/5 cm pc
REAR BUMPER PARKING SENSOR @ 235.00	4	\$940.00	shut 1 pc
REAR BUMPER PARKING SENSOR HARDNESS WIRE	1	\$285.00	11 X
TAIL LAMP @ 695.00	2	MSM \$1,390.00	0/5 cm pc
REAR END PANEL (LOWER)	1	\$215.00	BN
REAR END PANEL TOP GARNISH	1	\$195.00	11 X
REAR END PANEL (TOP)	1	\$377.00	0/3 cm
REAR EXHAUST SILENCER BOX	1	\$1,235.00	11 X
REAR EXHAUST HEAT SHIELD	1	\$135.00	11 X
REAR FENDER INNER GARNISH @ 358.00	2	\$716.00	11 X

Rear bumper top retainer

\$242 one

Less 10 %

Sub Total

\$13,331.50

\$1,333.15

\$11,998.35

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BOOT COVER BOARD CLIP	1	\$80.00	11 X
REAR WINDSCREEN GLASS SEALANT	1	\$100.00	11 X
REAR NUMBER PLATE	1	\$45.00	11 X
REAR CAMERA	1	\$650.00	11 X

Sub Total

\$875.00

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING & DIAGNOSTIC FUALD CODE		\$250.00	30
REMOVE AND REFIX REAR FENDER INNER TRIM REAR LUGGAGE PANEL CARPET ETC		\$200.00	80
REMOVE AND REFIX REAR WINDSCREEN GLASS		\$150.00	17X
APPLY ANTI RUST CHEMICAL		\$200.00	30
REMOVE AND REFIX REVERSING SENSOR		\$150.00	50
REMOVE AND REFIX EXHAUST PIPE AND RENEW		\$200.00	17X
KNOCK DENTS ON REAR DAMAGE PORTION, CUT, WELDING AND RENEW PARTS		\$1,800.00	1000
RESPRAY PAINTING		\$1,600.00	880

Sub Total \$4,550.00

Grand Total \$17,423.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 436890
100
3932.01
2070
6002.01
200
4801