

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLK 493K
speedmaster

at Workshop m/s

of

Insured:

SME 80765

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

882K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5
20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

4412

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 38706

Veh No:

SLK 493K

Yr Regn:

03/01/17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A/

AMG LINE

Make:

Mer Benz CLA 6

c.c

1595

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

82303

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 1173422N 407035

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

22/03/23

D.O.I.

27/3/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/17

seatbelt Actuated

11/4/23 4/5 @ 8000 in hand hurt

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

SPEEDWERKZ PRIVATE LIMITED
1 KAKI BUKIT AVENUE 6, #01-73, AUTOBAY, SINGAPORE 417883
Tel: 96195936 / info@speedwerkz.biz

not followed
27/3/23
2/5 \$8000
5 days

VEHICLE NUMBER: SLK493K
MAKE & MODEL: MERCEDES BENZ CLA 180 AMG LINE AUTO
DOA: 22.03.2023
CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BOOT COVER	1	R \$1,995.00	X
REAR BOOT LOCK	1	11 \$755.10	X
REAR BOOT RUBBER	1	11 \$322.70	X
REAR BOOT HINGES @ 86.20	2	11 \$172.40	X
REAR BOOT CENTRE LOGO	1	68.00 neu \$78.50	✓
REAR BOOT EMBLEM CLA180	1	72.00 neu \$86.00	✓
REAR BOOT INSULATOR	1	11 \$262.70	X
REAR TAIL LAMP @ 782.00	2	11/11 o/scre \$1,564.00	1 pc
REAR END PANEL	1	982.11 11/11 \$1,465.00	✓
REAR END PANEL TOP GARNISH	1	11 \$335.00	X
REAR SPARE TYRE PANEL	1	11 \$1,522.00	X
REAR SPARE TYRE PANEL TOP COVER	1	11 \$427.00	X
REAR BUMPER (AMG)	1	1628.11 11/11 \$2,420.00	✓
REAR BUMPER INNER CORNER RETAINER @ 117.20	2	65.00x2=130 cre \$234.40	✓
REAR BUMPER SIDE RETAINER @ 140.00	2	105x2=210 cre \$280.00	✓
REAR BUMPER REINFORCEMENT	1	715.32 11/11 \$1,095.00	✓
REAR BUMPER REINFORCEMENT BRACKET @ 224.00	2	11 \$448.00	X
REAR BUMPER LOWER BRACKET @ 48.30	2	11 \$96.60	X
REAR REVERSING SENSOR @ 232.00	4	190x2=380 11/11 \$928.00	2 pc
REAR REVERSING SENSOR HARDNESS WIRING	1	11 \$387.20	X
REAR BUMPER DIFFUSER	1	11/11 \$525.00	✓
REAR EXHAUST SILENCER	1	11 \$2,165.00	X
REAR EXHAUST CHROME PIPE @ 770.00	2	11 \$1,540.00	X
REAR LOCK KICKING SENSOR	1	11/11 \$275.00	✓
REAR LOCK KICKING SENSOR WIRE @ 82.00	2	11 \$164.00	X
REAR LOCK KICKING SENSOR HOLDER	1	11 cre \$65.70	✓
FRONT SEATBELT @1275	2	645. 11/11 Actual \$2,550.00	1 pc
REAR SEAT BELT @895	2	605 x2=1210 11/11 Actual \$1,790.00	✓
REAR SEAT LOCK	1	680 11/11 \$1,265.00	✓
AIRBAG ECU	1	11/11 \$1,399.00	X
REAR BUMPER REFLECTOR @ 186.00	2	11/11 \$372.00	X
REAR BUMPER LOWER CHROME GARNISH	1	under cover 522.00 11/11 \$985.00	✓
REAR BUMPER CENTRE RETAINER	1	182.50 11/11 \$375.00	✓
REAR BUMPER TOW COVER	1	11/11 \$60.00	✓
REAR EXHAUST SHIELD	1	11/11 \$315.00	X
REAR REVERSING O RING @ 12.00	4	11/11 \$48.00	X

\$28,768.30

Less 10 %

\$2,876.83

Sub Total

\$25,891.47

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BOOT INSULATOR CLIPS @ 6.00	10	11 \$60.00	X
REAR REVERSE CAMERA	1	11 \$750.00	X
REAR END PANEL TOP GARNISH CLIPS @ 6.00	3	11 \$18.00	X

18ef

REAR END PANEL SEALANT	1	her	\$80.00	50
REAR BUMPER LOWER CLIPS @ 6.00	18ef	her	\$48.00	✓
REAR NUMBER PLATE	1	11	\$45.00	X
Sub Total			\$1,001.00	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$200.00	20
TO DIGNOSTIC SRS WARNING LIGHT		\$350.00	} 150
REMOVE AND REFIX SAFETY BELT		\$250.00	
TUFF KOTE		\$200.00	30
REMOVE AND REPLACE EXHAUST PIPE		\$160.00	11 X
REMOVE AND REPLACE REVERSE SENSOR		\$160.00	50
TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING		\$1,800.00	680
TO SPRAY PAINTING AND ETC		\$1,800.00	800
Sub Total			\$4,920.00

Grand Total \$31,812.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 9112.74
 102
 8201.46
 98
 1730
 10029.4