

Not Authored
1/1/2023

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHB9586L

AAD2303-

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHB9586L

JTDKB3FU703082094

200303878K

TOYOTA

PRIUS

18/3/2023

GBJ4804U/III

27/6/2019

24 MAR 2023

PART

LIST

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

\$	Bu	558.39	—
\$	Bu	19.43	X
\$	Bu	148.58	X
\$	Bu	148.58	X
\$	Bu	111.41	X
\$	Bu	111.41	X
\$	nd/hu	726.92	✓
\$		419.90	?
\$	Bu	155.72	X
\$	Bu	155.72	X
\$	Bu	220.50	X
\$	Bu	304.92	X
\$	Bu	290.43	X
\$	Bu	159.39	X
\$	Bu	824.46	X

TOTAL \$ 4,355.72

25% \$ 1,088.93

\$ 3,266.79

SPECIAL NETT

1SET PARKING AID

- 1 REAR BUMPER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	Bu	700.00	X
\$	na	65.00	60.00
\$	na	65.00	X
\$	na	60.00	X
\$	NSP	180.00	X
\$	na	150.00	X
\$	na	200.00	X
\$	na	130.00	X

TOTAL \$ 1,550.00

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No Fax No. : 62571330
CO./ GST Reg. No. 2010196266
SHB95861

AAD2303-

TOTAL PARTS \$ 4,816.79

LABOUR

To rust-proofing of the affected areas. \$ *nn* 600.00 X

Putty and spray painting of the affected portion. \$ 1,200.00 *2201*

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 2,000.00 *2001*

To transfer of tailgate fittings and conduct water seepage test. \$ *nn* 170.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair. \$ *nn* 380.00 X

To reinstall rear bumper parking sensor. \$ 170.00 *501*

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test. \$ *nn* 170.00 X

TOTAL \$ 4,910.00

OVERALL TOTAL \$ 9,726.79

2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: