



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000356

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SLS4077K

Vehicle No. : CB7463E

Make & Model : TOYOTA HIACE

Chasis No. : KDH2010145934

Engine No. : 1KD2407265

Accident Date : 22/03/2023

Policy No. : D22MTSCBU000071

Date : 27/03/2023

Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	WHEEL BEARING (R/H/F) 11	1	PCS 351.95 X	351.95
2	SHOCK ABSORBER (R/H/F) 11	1	PCS 130.43 X	130.43
3	LOWER ARM (R/H/F) 11	1	PCS 437.14 X	437.14
4	FENDER (R/H/R) 11	1	PCS 1,086.80 X	1,086.80
5	Discount 25 %			-501.58
6	SubTotal (L)			1,504.74
7	STICKER "SCHOOL BUS" 111	1	PCS S/N 30.00 ✓	30.00
8	TYRE (R/H/R) 11	1	PCS 220.00 X	220.00
9	RIM 11	1	PCS 180.00 X	180.00
10	SubTotal (S)			430.00
11	PANEL BEATING & REPLACING OF THE ABOVE	1	X 200	1,000.00
12	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1	X 380	600.00
13	TO COMPUTERISE ADJUST WHEEL ALIGNMENT	1	X 60	120.00
14	TO APPLY UNDERCOATING TO ABOVE AFFECTED	1	X 11 X	120.00
15	TO CHECK UNDERCARRIAGE AND REPAIR DAMAGED PARTS	1	X 11 X	350.00
16	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1	X 11 X	180.00
17	SubTotal (LABOUR)			2,370.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not about
11/2 5 670
2 days.
28/3/23
the 2nd after repair.