

Fulco Autocare Pte Ltd

176 Sin Ming Drive #03-02 Sin Ming Autocare Singapore 575721
 Tel: (65) 6552 0302 Fax: (65) 6552 0780 Email: fulco0302@gmail.com

Make/Model: MITSUBISHI OUTLANDER

Date: 28/03/2023


Engine/Chassis No.: GF7W0700666

Claim Type: TP

Date of accident: 23.03.23

VRN: SMU8304G

Damaged area: Rear



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper	1	\$ 1,323.20	\$ 1,323.20
2	Rear bumper lower	1	\$ 547.00	\$ 547.00
3	Rear bumper reflector lamp	2	\$ 323.00	\$ 646.00
4	Rear bumper lower silver moulding	1	\$ 389.00	\$ 389.00
5	Rear bumper reflector inner bracket	2	\$ 36.00	\$ 72.00
6	Rear bumper side retainer	2	\$ 65.00	\$ 130.00
7	Rear bumper reinforcement	1	\$ 594.00	\$ 594.00
8	Rear bumper impact absorber LH/RH	2	\$ 115.00	\$ 230.00
9	Rear bumper tow cover	1	\$ 41.00	\$ 41.00
10	End panel upper	1	\$ 488.00	\$ 488.00
11	End panel top garnish	1	\$ 177.00	\$ 177.00
12	End panel top bracket	3	\$ 76.00	\$ 228.00
13	Tailgate	1	\$ 1,959.00	\$ 1,959.00
14	Rear windscreen moulding	1	\$ 135.00	\$ 135.00
15	Tailgate logo	1	\$ 105.00	\$ 105.00
16	Tailgate weatherstrip	1	\$ 189.00	\$ 189.00
17	Tailgate lock	1	\$ 412.00	\$ 412.00
18	Tailgate lock striker	1	\$ 75.00	\$ 75.00
19	Tailgate inner trimboard	1	\$ 577.00	\$ 577.00
20	Tailgate "C&C" emblem	1	\$ 88.00	\$ 88.00
21	Tailgate "MIVEC" emblem	1	\$ 55.00	\$ 55.00
22	Tailgate "OUTLANDER" emblem	1	\$ 65.00	\$ 65.00
23	Rear bumper reinforcement bracket	2	\$ 69.00	\$ 138.00
24	Keyless antenna	1	\$ 315.00	\$ 315.00
			Subtotal	\$ 8,978.20
			List discount	10.00%
			Total	\$ 8,080.38

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Reverse sensor	1	\$ 280.00	\$ 280.00
2	Rear bumper clips	12	\$ 5.50	\$ 66.00

Repair Estimate

3	End panel top garnish clips	8	\$ 5.50	\$ 44.00
4	Reverse camera	1	\$ 480.00	\$ 480.00
5	Tailgate inner trimboard clips	10	\$ 5.50	\$ 55.00
6	End panel sealant	1	\$ 100.00	\$ 100.00
7	Rear licence plate and frame	1	\$ 55.00	\$ 55.00
8	Rear windscreen sealant	1	\$ 80.00	\$ 80.00
9	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,210.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
6	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
Total labour			\$ 3,000.00

Estimate Grand Total	\$ 12,290.38
-----------------------------	---------------------