

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 04 Apr 2023

**Preliminary Advice**

Vehicle No	: SMF3562P	Accident Date	: 14/03/2023
Make	: PEUGEOT 3008	Policy No.	: SP2000616982
Assignment Date	: 25/03/2023	Excess	: S\$0.00
Date of Inspection	: 27/03/2023	Est. Duration of Repair	: 9
Inspection At	: VANTAGE AUTOMOTIVE LIMITED (ALEXANDRA) 305 ALEXANDRA ROAD #02-01, VANTAGE AUTOMOTIVE CENTRE SINGAPORE 159942		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,941.35
Revised Amount	:S\$	32,698.40
Check Items (Estimated)	:S\$	19,567.35
Total	:S\$	52,265.75

Lump Sum Repair	:S\$	40,000.00
-----------------	------	-----------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	42,644.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,356.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Repairer able to undertake the repair cost at \$40,000.00 on lump sum basic. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.