

Vehicle Damage Assessment Report for [SLD7988R]

Estimate Created: 22/06/2023 15:33 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 22/06/2023 15:44 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number	CDMPG23000721
Claim Type	OD		
Workshop	LKK_Auto_Consultants_Pt e_Ltd	Reference Number	

Vehicle Information

Brand	Mercedes-Benz	Model	C-Class
Engine Type			
License Plate Number	SLD7988R	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$5,950.00 WITH 3 WORKING
DAYS

Insurlogic 4 (22/06/2023 15:44)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Bonnet		1	1275.00	10.00 %	1,402.50
Bonnet lock		1	225.00	10.00 %	247.50
Front grille assy		1	650.00	10.00 %	715.00
Front bumper		1	1175.00	10.00 %	1,292.50
Front bumper car plate holder		1	120.00	10.00 %	132.00
Front bumper car plate set		1	60.00	10.00 %	66.00
o/s headlamp		1	2250.00	10.00 %	2,475.00
Front mounting console		1	275.00	10.00 %	302.50
Parts Subtotal					6,633.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	400.00	0.00 %	400.00
To check wiring and reset headlamp focussing.	RnR	30.00	0.00 %	30.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	400.00	0.00 %	400.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 430.00

Paint Labor Subtotal 400.00

Labor Subtotal 830.00

Summary

Repair Cost 7,463.00

Discount(20 %) (1,492.60)

5,970.40

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 5,970.40