

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT23/GBK1205M/TPC

QUOTATION

Dear Sir,

Cost of Repair to Vehicle GBK1205M

With reference to the above-mentioned, we are pleased to quote as follows:-


No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Tailgate 2101	1	3,698.70	bt 3,698.70
2.	Rear bumper 687	1	1,248.40	de 1,248.40
3.	Rear bumper center plastic garnish 169	1	236.70	de 236.70
4.	Tailgate rubber	1	- 214.90	X 214.90
5.	Tailgate centre emblem	1	42.80	ne 42.80
6.	Rear bumper clips	1	20.00	ne 20.00
7.	70KM/H sticker	1	15.00	ne 15.00
8.	Emergency door sticker	1	15.00	ne 15.00
9.	Rear Nissan NV350 emblem	1	89.00	ne 89.00
10.	Rear Nissan small emblem	1	73.00	ne 73.00
11.	Reverse Sensor	1	350.00	200nw 350.00
12.	Apply anti rust	1	120.00	30 120.00
13.	Company logo sticker	1	300.00	150 ne 300.00
14.	Check wiring	1	60.00	30 60.00
15.	Sealant	3	40.00	60 120.00
16.	Transfer tailgate fittings	1	150.00	60 150.00
17.	Labour to remove & refit rear windscreen	1	120.00	✓ 120.00
18.	Labour charges	1	1,000.00	600 1,000.00
19.	Spray painting	1	900.00	600 900.00

	SUB-TOTAL	SS8,773.50
--	------------------	-------------------

- Price before 7% gst

Thank you.

Yours faithfully



Winnie Chai
HP: 9850-9666

Tanpin 97495747
'WP' 14/11/23 @ 1220
05 days
4/5 Resurvey after repair
tanpin C (Kuantan) .com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: