

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
#01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584
Company Reg No: 201929175W

Repair Estimate

Vehicle number: SJX6875H
Make & Model: Nissan Sylphy
Chassis number: JN1BAAG11Z0111310

Date of survey:
Name of surveyor:
Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Rear bumper	1	\$ 686.90
2	Rear bumper clips	1set	\$ 80.00
3	Rear bumper RH reflector	1	\$ 66.60
4	Rear bumper RH reflector cover	1	\$ 58.90
5	Rear bumper chrome moulding	1	\$ 231.20
6	Rear bumper RH side retainer	1	\$ 51.30
7	Rear bumper LH side retainer	1	\$ 51.30
8	RH taillamp assy	1	\$ 453.60
9	RH taillamp panel	1	\$ 178.40
10	RH taillamp lock clips	1set	\$ 28.00
11	RH taillamp gasket	1	\$ 28.00
12	Rear windscreen glass rubber moulding	1	\$ 198.70
13	Rear RH fender	1	\$ 1,489.90
14	Rear RH fender glass with rubber	1	\$ 378.10
15	Rear RH fender inner trim board	1	\$ 418.90
16	Rear RH fender inner trim board clips	1set	\$ 80.00
17	Rear RH fender splash shield	1	\$ 93.20
18	Rear RH fender splash shield clips	1set	\$ 50.00
19	Rear RH fender petrol cover	1	\$ 78.30
20	Rear RH sport rim	1	\$ 873.20
21	Rear RH wheel bearing	1	\$ 428.60
22	Rear RH shock absorber	1	\$ 231.80
23	Rear axle beam	1	\$ 1,242.80
24	Rear RH door	1	\$ 1,015.60
25	Rear RH door chrome handle	1	\$ 211.40
26	Rear RH door frame black sticker no:1	1	\$ 19.20
27	Rear RH door frame black sticker no:2	1	\$ 19.50
28	Rear RH door frame black sticker no:3	1	\$ 31.60
29	Rear RH door chrome moulding	1	\$ 93.80
30	Rear RH door weatherstrip	1	\$ 118.20
31	Rear RH door inner trim board	1	\$ 539.10
32	Rear RH door inner trim board clips	1set	\$ 80.00
33	Rear RH door lock	1	\$ 268.90
34	RH side rocker panel garnish	1	\$ 639.10
35	RH side rocker panel garnish clips	1set	\$ 80.00

\$ 10,594.10

Parts less 10% \$ 1,059.41

Total \$ 9,534.69

No.	Special Nett Items	Qty	Amount S\$

1	Rear windscreen glass sealant	1	\$ 400 80.00
2	Rear windscreen glass inner seal	1	\$ 300 60.00
3	Rear RH tyre	1	\$ cut 200 500.00
4	Rear RH fender glass sealant	1	\$ ne 50.00
5	Rear RH fender glass inner seal	1	\$ ne 30.00
6	Rear RH fender joint sealant	1	\$ cut 40 80.00
Total:			\$ 800.00

80%

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 800 1,600.00
2	Spray painting on affected areas and panels	\$ 700 1,400.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 100.00
5	Remove and reinstall roof lining, seats and carpet to assist repair	\$ 60 320.00
6	Remove and reinstall rear windscreen glass to assist repair	\$ 120 220.00
7	Remove and reinstall fuel tank pipes, sensors and sensors to assist repair	\$ 60 180.00
8	Remove and reinstall rear bumper reverse sensors to assist repair	\$ 80 100.00
9	Remove and reinstall rear inner garnish and trims to assist repair	\$ 60 280.00
10	Test drive and adjust wheel alignment system	\$ 80 180.00
11	Remove and replace rear undecarriage parts to assist repair	\$ 750? 480.00
12	Remove and replace rear RH door inner mechansim to new door	\$ 60 120.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

Spare Parts: \$ 9,534.69
Special Nett: \$ 800.00
Labour: \$ 5,060.00
Total Amount: \$ 15,394.69

Tanpin 47495449
WP 28/3/23 @1045
tanpin @ kharto.com
06 days
L/S Repair after repair
- To check consistency of accident
- To check ~~the~~ part prices