

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906057G

Estimated Cost of Repair

Attention To : India International Insurance
Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Claim Details

Case Ref. No. : TP/032023/6086
Date : 09-03-2023
Accident Date : 06-03-2023

Vehicle Details

Make & Model : Subaru FORESTER 2.0I-L CVT
AWD SR
Chassis No : JF1SJ5KC5JG100072
Registration No : SLU4336C

Third Party Vehicle Details

Registration No : SLK9211Z

S/N	Description	Qty	Amount (\$)
			\$540.30
1	REAR BUMPER <i>AV</i>	1.00	\$310.50 <i>170</i>
2	REAR BUMPER STEP GARNISH <i>% IVCC</i>	1.00	\$14.10
3	REAR BUMPER TOWING COVER <i>MISSING</i>	1.00	\$28.20
4	REAR BUMPER LH REFLECTOR ? <i>cut</i>	1.00	\$18.50
5	REAR BUMPER LH COVER (EXHAUST) ? <i>de</i>	1.00	\$325.10
6	REAR BUMPER REINFORCEMENT ? <i>bl</i>	10.00	\$45.00 <i>30</i>
7	REAR BUMPER CLIPS <i>NLC</i>		
			\$1,281.70
			(\$256.34)
			\$1,025.36
8	REAR BUMPER PARKING SENSOR <i>Faulty</i>	1.00	<i>200</i> \$380.00
9	TO REPAIR DAMAGES	1.00	<i>200</i> \$580.00
10	TO SPRAY PAINTING	1.00	<i>280</i> \$680.00
			\$2,665.36

Discount: -20%

Subtotal w/o GST:

3 days
P/P LHS *1 rfm*
2713123 *90097659*
4-30pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This report is prepared on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- This is a computer-generated document. No signature is required.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total w sup = 2054.50

20% = 410.90

= 1643.60

F-T = 2323.60

20% = 464.72

*= 1858.88 ≈ 1850**

1 of 1

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair (Supplementary)

SG41110R MCE

Attention To : India International Insurance
Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Claim Details
Case Ref. No. : TP/032023/6086
Date : 09-03-2023
Accident Date : 06-03-2023

Vehicle Details

Make & Model : Subaru FORESTER 2.0I-L CVT
AWD SR

Chassis No : JF1SJ5KC5JG100072

Registration No : SLU4336C

Third Party Vehicle Details
Registration No : SLK9211Z

S/N	Description	Qty	Amount (S\$)
1	REAR END PANEL	1.00	358.30 ✓
2	REAR SPARE TYRE PANEL	1.00	572.40 ✓ 400
3	REAR TOOL BOX	1.00	244.10 ✓ 170
			\$1,174.80
			(234.96)
Discount: -20%			\$939.84
4	TO REPLACE REAR END PANEL, SPARE TYRE PANEL, AND TOOL BOX	1.00	400.00 ✓
5	TO SPRAY PAINT REAR END PANEL, SPRARE TYRE PANEL, AND TOOL BOX	1.00	400.00 ✓

Subtotal w/o GST: \$1,739.84

Lumpsum
Resumy after repair.
5 days.
Tanglin 28/3/23

Issued by Elaine Lee

This is a computer-generated document. No signature is required.