



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23003137/Uny3q2	
			Date: 14/04/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMR 1008Z	Veh. Inspected	YN 1322U
	Policy No.	D22MTPV01018211	Coverage (\$)	0.00
	Claim No.	CMTD2301147/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	27/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi FE84	c.c	2977
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	FE84BEA20113	Colour	YELLOW
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	7.00 R16	ADVANCE	6 mm
	L/H Front Tyre	7.00 R16	ADVANCE	6 mm
	R/H Rear Tyre	7.00 R16 (D)	ADVANCE	6/6 mm
	L/H Rear Tyre	7.00 R16 (D)	ADVANCE	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/03/2023	Inspection Date	28/03/2023
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	