



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC23003138/Avy3m4

Date: 23/05/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 6652K	Veh. Inspected	SFQ 3388B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1215081-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	27/03/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	MR053REH104515734	Colour	BROWN
Odometer	227758 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	TOURADOR	6 mm
L/H Front Tyre	205/55R16	TOURADOR	6 mm
R/H Rear Tyre	205/55R16	TOURADOR	6 mm
L/H Rear Tyre	205/55R16	TOURADOR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/03/2023	Inspect Date / Time	28/03/2023 (02:28 PM)
Survey held at	AP AUTOMOTIVE SERVICES PTE LTD 9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**