

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23003142/AYA3Q2**Date:** 20/06/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002880336
Claimant Vehicle No :	PZ644R	Insured Vehicle No :	PC3822U
Date of Loss:	22/02/2023	Nature of Claim:	TP
		Claim No:	202332005720

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PZ644R	Engine No:	DC13115K017203635
Make & Model:	SCANIA KIB4X2, 12.7 D (M)	Chassis No:	YS2K4X20001916080
Reg. Date:	11/08/2021 (Man. Year: 2019)	Odometer:	39571 km
Colour:	White		
Engine Capacity:	12742 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,890.00	7,910.00	10,980.00	58.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,050.00	2,110.00	3,940.00	65.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,940.00	10,020.00	14,920.00	59.82
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	24,940.00	8,000.00	16,940.00	67.92
+ Loss of Use (6.0 x S\$150.00/day) (S\$)		900.00		
Nett Liability (S\$)		8,900.00		

INSPECTION

Date of Assignment:	02/03/2023	
Date Inspected:	02/03/2023	Inspected At: YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Jun 2023)	
Parts:	N/A	SCANIA KIB4X2 12.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PZ644R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,500.00 FS	*- FS
2	1		*HEADLAMP	Not Necessary	2,000.00 FS	*- FS
3	1		*FRONT BATTERY COMPARTMENT COVER	Buckled	1,000.00 FS	*600.00 FS
4	1		*FRONT BATTERY COMPARTMENT COVER LOCK	Not Necessary	200.00 FS	*- FS
5	1		*FRONT BATTERY COMPARTMENT COVER LOCK HANDLE	Cut	100.00 FS	*100.00 FS
6	1		*FRONT RH BODY PANEL	Dented	1,800.00 FS	*1,200.00 FS
7	1		*FRONT RH BODY PANEL GLASS OUTER GARNISH	Cracked	380.00 FS	*300.00 FS
8	1		*SCANIA LOGO	Necessary	350.00 FS	*200.00 FS
9	1		*SCANIA WORDING	Necessary	250.00 FS	*150.00 FS
10	1		*FRONT RH WHEEL PANEL	Repair	1,500.00 FS	*- FS
11	1		*FRONT RH WHEEL PANEL ARC GARNISH	Cracked	500.00 FS	*400.00 FS
12	1		*FRONT RH WHEEL PANEL SIGNAL LAMP	Cracked	150.00 FS	*100.00 FS
13	1		*FRONT RH WHEEL RIM COVER	Cut	500.00 FS	*300.00 FS
14	10		*FRONT RH WHEEL RIM NUT COVER	Damaged (3 PCS ONLY)	300.00 FS	*60.00 FS
15	1		*FRONT RH WING MIRROR ASSY	Damaged	3,800.00 FS	*3,000.00 FS
16	1		*FRONT WINDSCREEN PANEL TOP SPOILER	Cracked	2,000.00 FS	*1,500.00 FS
17	1		*FRONT WINDSCREEN MOULDING	Not Necessary	380.00 FS	*- FS
18	1		*FRONT WINDSCREEN SEALANT	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 18,890.00 7,910.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVE AND REFIT PARTS	New	2,800.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	2,500.00	1,200.00
3	WIRING CHECK	New	150.00	30.00
4	TO APPLY TUFF COAT	New	200.00	80.00
5	TO REMOVE FRONT WINDSCREEN	New	400.00	0.00
Gross Labour Cost (S\$)			6,050.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >