

ASS. RES. CB. Taufikh

REF:

CS/IM/23003143/1793.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV

To Insp. ed Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

WP.

Ms. Loh

Date/Time Action/Instruction

Battery weak

Taufikh finalised LS \$2350, 3 days. (Red \$2947.08, 56%)

Veh No: SMA2097MYr Regn: 2017 Jan

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140c.c. 1685Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCB.414MA4098272

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NIL / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRI / SUMI /TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 27/3/23Survey held at airport bayDes. of Damages Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) 22/05 Typist☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Rep. Format: MER-TPLump Sum 2350

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)**CTPL**

Loke Wei Yiang

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	24/03/2023
Vehicle Reg. No.:	SHA2097H	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	25/01/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU706201	Chassis No:	KMHLB41UMHU098272
Odometer:	558010 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	3,546.08
Miscellaneous Items	71.00
Labour	1,680.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,297.08
+ GST 8.00% (\$\$)	423.77
Nett Amount (\$\$)	5,720.85

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Mar 2023)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA2097H/27/03/2023 09:54**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00 <i>de</i>	*553.00 FL
2	1		*REAR BUMPER CLIPS	20.00	0.00 <i>net</i>	*22.00 FL
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00 <i>Cur</i>	*428.40 FL
4	1		*RR BUMPER REINFORCEMENT BRACKET LH	20.00	0.00 ?	*160.60 FL
5	1		*RR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00 ?	*160.60 FL
6	1		*REAR BUMPER BRACKET LH	20.00	0.00 X	*35.60 FL
7	1		*REAR BUMPER BRACKET RH	20.00	0.00 X	*35.60 FL
8	1		*REAR BUMPER UNDER COVER	20.00 <i>de</i>	0.00 <i>By</i>	*228.00 FL
9	1		*REAR BUMPER REFLECTOR LAMP LH	20.00	0.00 <i>Cur</i>	*32.00 FL
10	1		*REAR BUMPER REFLECTOR LAMP RH	20.00	0.00 <i>net</i>	*32.00 FL
11	1		*EXHAUST SILENCER LH	20.00	0.00 X	*967.70 FL
12	1		*EXHAUST SILENCER RH	20.00	0.00 X	*967.70 FL
13	1		*REAR END PANEL GARNISH	20.00	0.00 <i>de</i>	*57.70 FL
14	1		*REAR PANEL	20.00	0.00 <i>bt</i>	*526.70 FL
15	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00 <i>u</i>	*180.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,387.60
- List Item Discount on L Items (\$\$)	841.52
Total Parts (\$\$)	3,546.08

ComfortDelGro Engineering Pte Ltd/SHA2097H/27/03/2023 09:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	TOWING FEE	60.00
2	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			71.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	900.00
2	SPRAY PAINTING CHARGE	New	600.00
3	REMOVE/REFIX EXHAUST	New	120.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00
Gross Labour Cost (S\$)			1,680.00

ComfortDelGro Engineering Pte Ltd/SHA2097H/27/03/2023 09:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495744
wp, 27/3/23 @ 3:50pm
2/3 hours after repair
Tanpin @ 11 hours
03 days

4

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road Singapore 508693

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

A member of COMFORTDELGRO

Date/Time: 27.03.2023 09:47

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5890868

JC NO: 305549649

STOMER
COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (R) (O)
(P)


REGN NO: SHA2097H	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 24.03.2023 17:55
YR OF MANU. 25.01.2017	TARGET DATE
CHASSIS CODE KMHLB41UMHU098272	COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 24.03.2023
NATURE: 3P 24.03.2023

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Weldgement Slip

Exit Pass

No.: SHA2097H YY

Vehicle No.: SHA2097H

of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard