

NOT AUTHORIZED
Preserving B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF564M

AAD2303-069

8 5932.88
5892.88

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 MAR 2023

SHF564M

JTDKB3FUX03093722

200303878K

TOYOTA

PRIUS GEN 4

23/3/2023

SMV3883D/ERGO

29/1/2021

PART

- 1 PANEL SUB-ASSY, FRONT DOOR, LH
- 1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH
- 1 HANDLE ASSY, FRONT DOOR OUTSIDE, LH
- 1 WEATHERSTRIP, FRONT DOOR, LH
- 1 HINGE ASSY, FRONT DOOR, LOWER LH
- 1 HINGE ASSY, FRONT DOOR, UPPER LH
- 1 TAPE, BLACK OUT, NO.1 FRT LH
- 1 TAPE, BLACK OUT, NO.2 FRT LH
- 1 TAPE, BLACK OUT, NO.3 FRT LH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 ABSORBER ASSY, SHOCK, FRONT LH
- 1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH
- 1 KNUCKLE, STEERING, LH
- 1 RIM
- 1 HUB CAP
- 1 FENDER SUB-ASSY, FRONT LH
- 1 BRACE SUB-ASSY, FENDER APRON, LH
- 1 LINER, FRONT FENDER, LH
- 1 EMBLEM, SIDE PANEL
- 1 COVER, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH

LIST

\$	R	1,641.36	✓
\$	R	243.81	X
\$	R	493.40	X
\$	R	292.32	X
\$	R	139.86	X
\$	R	123.06	X
\$	R	16.91	✓
\$	R	55.02	✓
\$	R	33.29	✓
\$	R	1,161.83	X
\$	R	300.62	X
\$	R	3,325.56	X
\$	R	596.19	X
\$	R	959.81	X
\$	R	836.64	✓
\$	R	1,995.11	X
\$	R	222.08	✓
\$	R	1,236.69	✓
\$	R	368.24	X
\$	R	265.55	✓
\$	R	68.88	✓
\$	R	659.40	✓
\$	R	100.49	✓
\$	R	59.85	X
\$	R	74.97	X

Trans-cab Auto Services Pte Ltd

AAD2303-069

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF564M

- 1 MOULDING, FRONT BUMPER SIDE, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH

\$	CM	120.86	✓
\$	R	624.54	X
TOTAL	\$	16,016.34	
25%	\$	4,004.09	
	\$	12,012.26	

Special Nett

- 1SET DOOR TRIM CLIP
- 1SET DOOR WEATHERSTRIP CLIP
- 1 DOOR STICKER TRANSCAB
- 1 TYRE
- 1SET CLIP, ROCKER PANEL MOULDING
- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

\$	na	70.00	X
\$	na	65.00	X
\$	na	100.00	601
225IN \$	CV	350.00	901IN
\$	na	65.00	X
\$	na	65.00	601
\$	na	85.00	X
\$	na	130.00	X
\$	na	65.00	✓
TOTAL	\$	995.00	

TOTAL PARTS \$ 2,300.00**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	501
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	881

Trans-cab Auto Services Pte Ltd**AAD2303-069**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF564M

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *201*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To check steering geometry and computer wheel alignment

\$ 220.00 *601*

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL \$ 5,100.00****Over All Total \$ 19,412.26****(PART-BY-PART) Repair Days*****08-Days****4 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: