

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Dep PIR

Report case

6/4/23

2/5 @ 2100 inspect Alan (Used @ 4536.30, 68%)

Veh No:

SNA 4757C

Yr Regn:

26/11/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mod Jaz

c.c

1318

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

71566

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JH/MGK 3850L S207707

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/03/23

D.O.I.

27/3/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rep.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1/6/4 trip

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

TP

Lump Sum / I.B.I. (\$

2100

TOTAL

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

not Avland
for
verand
27/3/23
1/5 \$2100/
3 days

VEHICLE No: SNA 4757C

1PC	FRONT BUMPER	Deep cut	\$61.20	\$821.90
1PC	FRONT BUMPER SIDE RETAINER O/S	surf	35.50	\$65.50
1SET	FRONT BUMPER CLIPS	111		\$39.00
1PC	FRONT BUMPER REINFORCEMENT	11		\$387.80
1PC	FRONT BUMPER FOG LAMP O/S	11		\$366.50
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	11		\$381.90
1PC	HEADLAMP LED O/S	holder cut	1322.30	\$1,815.20
1PC	HEADLAMP LOWER BRACKET O/S	115		\$66.80
1PC	FRONT FENDER O/S	DD	421.30	\$455.20
1PC	FRONT FENDER INNER SHIELD O/S	11		\$166.20
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	11		\$39.00
1PC	FRONT FENDER INNER ARCH PANEL O/S	R	202	\$291.30
				\$4,896.30

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM
TO CONDUCT WHEEL ALIGNMENT
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
	\$50.00	30
11	\$120.00	X
11	\$120.00	X
	\$600.00	300
	\$800.00	400
TOTAL	\$6,636.30	

2-2379.30
202
1903.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: