

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 25.03.2023

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJE7122R**
MODEL : **HONDA CIVIC**
DATE OF ACCIDENT : 25.03.2023
TIME OF ACCIDENT : 10:45 HOURS

Ezlynn.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL - PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Deformed</i>	1	\$ 698.60	\$ 698.60
2	REAR BUMPER SIDE RETAINER <i>Brkd</i>	2	\$ 39.40	\$ 78.80
3	REAR BUMPER EXHAUST GARNISH <i>New</i>	1	\$ 38.90	\$ 38.90
4	REAR FENDER INNER TRIM <i>New LH Dehd</i>	2	\$ 249.90	\$ 499.80
5	TAILLAMP <i>Crashd</i>	2	\$ 299.60	\$ 599.20
6	TAILLAMP LOWER BRACKET <i>New</i>	2	\$ 29.10	\$ 58.20
7	BOOTLID <i>Dented</i>	1	\$ 695.70	\$ 695.70
8	BOOTLID NUMBER PLATE GARNISH <i>New</i>	1	\$ 128.30	\$ 128.30
9	BOOTLID NUMBER PLATE LAMP <i>New</i>	2	\$ 65.20	\$ 130.40
10	BOOTLID REFLECTOR <i>New</i>	2	\$ 199.80	\$ 399.60
11	BOOTLID INSULATOR <i>New</i>	1	\$ 187.60	\$ 187.60
12	BOOTLID INNER STOPPER <i>New</i>	4	\$ 18.00	\$ 72.00
13	BOOTLID HINGE <i>New</i>	2	\$ 48.00	\$ 96.00
14	BOOTLID TOP LOCK <i>Brkd</i>	1	\$ 194.90	\$ 194.90
15	BOOTLID LOWER LOCK <i>New</i>	1	\$ 15.00	\$ 15.00
16	BOOTLID LOGO <i>New</i>	1	\$ 39.40	\$ 39.40
17	BOOTLID EMBLEM '1.8'	1	\$ 17.00	\$ 17.00
18	BOOTLID EMBLEM 'V-TECH'	1	\$ 37.10	\$ 37.10
19	BOOTLID EMBLEM 'CIVIC'	1	\$ 29.10	\$ 29.10
20	BOOTLID WEATHER STRIP <i>Cr</i>	1	\$ 154.00	\$ 154.00
21	REAR END PANEL <i>Dented</i>	1	\$ 387.30	\$ 387.30
22	REAR END PANEL TOP GARNISH <i>Deformed</i>	1	\$ 127.80	\$ 127.80

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJE7122R**
 MODEL : **HONDA CIVIC**
 DATE OF ACCIDENT : 25.03.2023
 TIME OF ACCIDENT : 10:45 HOURS

23	REAR FLOOR PANEL TOP BOARD <i>Defunct</i>	1	\$	316.00	\$	316.00	✓
----	---	---	----	--------	----	--------	---

3624.80

2899.84

TOTAL PRICE \$ 5,000.70
 LESS 20% \$ 1,000.14
SUB TOTAL PRICE \$ 4,000.56

S/N	DESCRIPTION	QTY	UNIT	S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$	50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$	50.00	\$ 50.00	30
3	REAR BUMPER EXHAUST GARNISH CLIP (SET) <i>new</i>	1	\$	30.00	\$ 30.00	+
4	TAIL LAMP CLIP (SET) <i>new</i>	1	\$	30.00	\$ 30.00	20
5	BOOTLID INSULATOR CLIP (SET) <i>new</i>	1	\$	50.00	\$ 50.00	+
6	BOOTLID NUMBER PLATE LAMP COVER GARNISH CLIP (SET) <i>new</i>	1	\$	20.00	\$ 20.00	+
7	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$	60.00	\$ 60.00	+
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$	50.00	\$ 50.00	10
9	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$	150.00	\$ 150.00	60
10	REVERSE SENSOR <i>Damaged</i>	1	\$	220.00	\$ 220.00	20
11	REAR EXHAUST CHROME PIPE (SPECIAL TYPE) <i>new</i>	1	\$	280.00	\$ 280.00	+

320

TOTAL \$ 990.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 280.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJE7122R**
MODEL : **HONDA CIVIC**
DATE OF ACCIDENT : 25.03.2023
TIME OF ACCIDENT : 10:45 HOURS

8	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,760.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,990.56
TOTAL LABOUR COST : \$ 4,760.00
TOTAL REPAIR COST : \$ 9,750.56

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian Lj
2/c 28/03/23.

06 Days.

total: 5079.84

4/s: 4050 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: