

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No. : SKU 4964 B
 Chassis No. : WBAWX52070LK44479
 Engine No. : 01407664N52B30AF
 Date of Accident : 24.03.2023

Reference No. : 230324-TPC-JSSM09
 Make/Model : BMW / X3 XDRIVE28I 3.0
 Date : 28.03.2023

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Rear Bumper	Scratched	\$ 1,590.00	\$ 1,431.00
2	1	Rear Bumper Garnish	Scratched	\$ 228.00	\$ 205.20
3	1	Rear Bumper RH Reflector	Damaged	\$ 118.00	\$ 106.20
4	1	Rear RH Wheel Trim Garnish	Necessary	\$ 289.00	\$ 260.10
5	1	Rear RH Wheel Cowling	Necessary	\$ 199.00	\$ 179.10
6	1	Rear RH Fender	Dented	\$ 2,166.00	\$ 1,949.40
7	1	Rear RH Door	Necessary	\$ 1,880.00	\$ 1,692.00
8	1	Rear RH Door Trim Garnish	Necessary	\$ 280.00	\$ 252.00
9	1	RH Side Skirt	Scratched	\$ 499.00	\$ 449.10
10	1	Rear RH Sport Alloy Rim	Necessary	\$ 890.00	\$ 801.00
				\$ 8,139.00	\$ 7,732.05

Total (Parts) \$ 8,139.00 -5% \$ 7,732.05

Labour Charges

- Rear*
- To fix & dismantle and remove damaged Front Portions; affected damaged portion.
 - To apply anti rust coat and affected areas
 - To check wiring
 - Welding and cutting of affected panels, including chassis alignment.
 - Spray painting for Front Portions affected parts
 - Refocusing of the front headlamp
 - Diagnose ECU system and reset error code.
 - 3D Wheel Alignment
 - To Apply Waterproofing sealer on Front Support Panels

Total Labour: \$ 1,820.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 9,552.05

\$ 9,552.05

JSSM AUTOSOLUTIONS PTE LTD

\$ 2540.00
 Page 1

LKK Auto Consultants here
 the repairer of the following
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
 Date: _____

Akid 8700 5621
 04 days
 03/04/23 2015hrs

LKK Auto Consul
 the Repairer of the following
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____