

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

27 MAR 2023

ESTIMATE

Estimate No. : b1 65435
Date Estimated : 27/03/2023
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Wang Yifan
30 Tanah Merah Kechil Road
#11-03

Singapore 465558

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNG6892A	WBA32AN0X07L01658	26/08/2022	216i Gran Coupe	10629

DESCRIPTION

To replace rear bumper including to knock boot lid, tail panel and dented area

To respray rear bumper, boot lid and tail panel

To remove and install boot compartment carpet and garnish to facilitate repair.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To check electrical wiring system and lighting at the rear section for proper function.

To supply rear emboss number plate. 14/

Sundries.

VALUE

2,875.00

2,666.00

271.00

177.00

177.00

83.00

80.00

Total Labour 1: 6,429.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
C CLIP FOR PLASTIC NUT	10	1.10	11.00
SMART OPENER MOUNTING	1	48.45	48.45
# REAR BUMPER CARRIER	1	505.35	505.35
# REAR BUMPER BOTTOM TRIM PANE	1	207.30	207.30
# REAR CENTRE GUIDE	1	163.55	163.55
# LH BUMPER TOP GUIDE	1	77.90	77.90
RH BUMPER TOP GUIDE	1	77.90	77.90
# REAR BUMPER PANEL PRIMED (PD	1	1,088.30	1,088.30
REAR TOWING EYE COVER PRIMED	1	45.25	45.25
EMBLEM GROMMET	2	0.95	1.90
# LETTERING (216i)	1	65.60	65.60
BMW EMBLEM 82MM	1	72.85	72.85
# REAR BUMPER HEAT INSULATION	1	80.75	80.75

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 65435
Date Estimated : 27/03/2023
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNG6892A	WBA32AN0X07L01658	26/08/2022	216i Gran Coupe	10629

DESCRIPTION	QTY	PRIC	VALUE
DECOUPLING RING <i>✓</i>	2	5.30	10.60
ULTRASONIC SENSOR MINERAL WHITE WA9 <i>7.4m</i>	2	386.00	772.00
Total Parts :			3,228.70

Claims (G/L) and Part / Uninsured losses / Direct Settlement

Page No. 08/03/23 P14W Claim No. 900610068

Date & Time 08/03/23 Excess S\$ RBm

Signature RBm Sign RBm

Surveyor's E-mail RBm Authorised Yes / No Yes

Approved Date 08/03/23 Date 08/03/23

Resurvey & Painted Photo by Surveyor Yes / No Yes PMI Yes / No No

Surveyor's E-mail RBm

Maximum Repair Period 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Labour 1	:	6,429.00
Parts	:	3,228.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	772.62
Grand Total	:	10,430.32

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **