

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC7251K

14.03.2023

MAKE REG. 10.08.2016

MODEL HYU- I40

CHIANG/ CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$553.00	/ CRA
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20	Y L? / CRA
10	REAR BUMPER CLIPS		\$2.20	\$22.00	/ NF
1	REAR BUMPER REFLECTOR /RH		\$32.00	\$32.00	/ CRA
1	REAR BUMPER REINFORCEMENT			\$428.40	?
1	REAR BUMPER UNDER COVER			\$228.00	?
1	BOOTLID			\$2,609.80	/ DD
1	BOOTLID HINGES LH/RH		\$142.30	\$284.60	?
1	BOOTLID LAMP /RH		\$565.60	\$565.60	/ CRA
1	TAIL LAMP LH/RH		\$697.80	\$697.80	/ CRA
1	BOOTLID MOULDING			\$85.00	/ NEL
2	NO PLATE LAMP LH/RH		\$56.10	\$112.20	
1	REAR FENDER RH			\$2,171.40	/ DD
1	TAIL LAMP PANEL /RH		\$225.60	\$225.60	?
1	REAR END PANEL GARNISH			\$51.60	?
1	REAR FENDER AIR DUCT RH			\$52.40	?
1	BOOTLID CDRI			\$67.90	/ NEL
1	BOOTLID EMBLEM I40			\$8,258.50	
	SUB TOTAL			\$1,651.70	
	20.00%			\$6,606.80	
	DISCOUNTED TOTAL				
1	BOOTLID COFORT & TEL NO. STICKER			\$80.00	/ NF
1	REVERSE SENSOR			\$135.70	/ NEL
				\$215.70	
	Labour Charge				
	Panel Beating			\$1,200.00	840
	Spray Painting Charge			\$800.00	750
	Remove/Refix rRear Upholstery			\$90.00	30
	Remove/refix reverse sensor			\$60.00	30
	Check lighting			\$60.00	30
	Tuff Kote			\$90.00	40
	TOTAL LABOUR			\$2,300.00	
	ESTIMATE TOTAL			\$ 9,122.50	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NA 2 CXK

15/3/2023 / 605

L/S

4 Days

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS