

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



Xiao Tong

DATE : 07.03.2023

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SKK1661Y
MODEL : BMW 520I
DATE OF ACCIDENT : 28.02.2023
TIME OF ACCIDENT : 15:30 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>torn</i>	1	\$ 1,688.20	\$ 1,688.20
2	FRONT BUMPER SENSOR RH <i>Not new</i>	2	\$ 249.95	\$ 499.90
3	FRONT BUMPER BOTTOM SIDE GARNISH RH <i>Not new</i>	1	\$ 64.75	\$ 64.75
4	FRONT BUMPER SIDE BRACKET <i>3 for</i>	2	\$ 36.20	\$ 72.40
5	FRONT BUMPER CORNER INNER SUPPORT RH <i>for</i>	1	\$ 78.50	\$ 78.50
6	FRONT BUMPER REINFORCEMENT	1	\$ 726.70	\$ 726.70
7	FRONT BUMPER SPONGE <i>crushed</i>	1	\$ 63.00	\$ 63.00
8	FRONT GRILLE C/W CHROME <i>crushed</i>	2	\$ 145.70 291.40	\$ 291.40
9	FRONT GRILLE WIND AIR GUARD <i>crushed</i>	1	\$ 285.80	\$ 285.80
10	FRONT GRILLE SIDE BRACKET <i>crushed</i>	2	\$ 36.20	\$ 72.40
11	FRONT LOWER GRILLE (CENTER) <i>new</i>	1	\$ 99.80	\$ 99.80
12	FRONT LOWER GRILLE AIR GUARD <i>new</i>	1	\$ 98.10	\$ 98.10
13	FRONT LOWER GRILLE (SIDE) <i>new</i>	2	\$ 116.45	\$ 232.90
14	FRONT LOWER SIDE GRILLE COVER GARNISH <i>new</i>	2	\$ 78.80	\$ 157.60
15	HEADLAMP (LED) <i>crushed</i>	2	\$ 5,346.20	\$ 10,692.40
16	HEADLAMP TOP RUBBER RH <i>new</i>	1	\$ 44.60	\$ 44.60
17	HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$ 48.60	\$ 48.60
18	BONNET <i>crushed</i>	1	\$ 3,525.30	\$ 3,525.30
19	BONNET LOGO <i>new</i>	1	\$ 71.50	\$ 71.50
20	BONNET HINGE <i>new</i>	2	\$ 93.20	\$ 186.40
21	BONNET LOCK <i>Not new</i>	2	\$ 265.40	\$ 530.80

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SKK1661Y
 MODEL : BMW 520I
 DATE OF ACCIDENT : 28.02.2023
 TIME OF ACCIDENT : 15:30 HOURS

22	BONNET INSULATOR <i>xh m</i>	1	\$ 256.55	\$ 256.55	<i>+</i>
23	BONNET LOCK CATCHER <i>2</i>	2	\$ 65.20	\$ 130.40	<i>+</i>
24	BONNET LOCK STOPPER <i>2</i>	2	\$ 65.20	\$ 130.40	<i>+</i>
25	FRONT AIR DUCT RH	1	\$ 51.80	\$ 51.80	<i>+</i>

16690
15855.50
 TOTAL PRICE \$ 20,100.20
 LESS 5% \$ 1,005.01
 SUB TOTAL PRICE \$ 19,095.19

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE (SPECAIL TYPE) <i>xh m</i>	1	\$ 180.00	\$ 180.00	<i>+</i>
2	FRONT BUMPER CLIP (SET) <i>m</i>	1	\$ 120.00	\$ 120.00	<i>50</i>
3	FRONT BUMPER BOTTOM SIDE GARNISH CLIP (SET) <i>xh m</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
4	FRONT BUMPER BOTTOM GARNISH CLIP (SET) <i>2</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
5	FRONT LOWER GRILLE (SIDE) CLIP (SET) <i>2</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
6	BONNET SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
7	BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>x.</i>
8	FRONT AIR GUARD GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
9	FRONT AIR GUARD TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
10	FRONT FENDER INNER COWLING CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>x.</i>

110 TOTAL \$ 910.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	500
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>x</i>
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>x</i>
5	REMOVE AND REFIX FRONT WIRING	\$ 280.00	30
6	RESET AND REPROGRAMMING HEADLAMP SYSTEM	\$ 580.00	<i>x</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SKK1661Y
MODEL : BMW 520I
DATE OF ACCIDENT : 28.02.2023
TIME OF ACCIDENT : 15:30 HOURS

7	REMOVE AND REFIX FRONT BUMPER SENSOR	\$ 80.00	50
8	REMOVE AND REFIX AND RESET FRONT GRILLE WIND MOTOR	\$ 450.00	x
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 580.00	x 150

1330

TOTAL \$ 5,170.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 20,005.19
TOTAL LABOUR COST : \$ 5,170.00
TOTAL REPAIR COST : \$ 25,175.19

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian Lj
h/s 07/03/23.
04 Days

Total 61729550
h/s: 13.81c

13.81c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: