

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0306/2023/EQ
DATE : 24-Mar-23
WIP : 13691

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS PRISCILLA LEONG SAU PENG
ADDRESS : 19 ENG KONG ROAD
SINGAPORE 596144

TELEPHONE : HP +65 91770268
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SFG 3282 A**
MODEL CODE : AUDI Q5 2.0 TFSI
MODEL YEAR : 31/12/2015
ENGINE NO : CNC 145907
CHASSIS NO : WAUZZZ8R8GA066219
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Mar-22
PLACE OF ACCIDENT : CARPARK EXIT OF CHINATOWN FOOD MARKET CENTRE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFG 3282 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X
2	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280 /
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	?
4	TO REMOVE AND REINSTALL DASHBOARD ASSY TRIM TO FACILITATE REPAIR OF RHS A-PILLAR.	S/N \$ 480.00	?
5	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS A-PILLAR BRACKET. TO REPAIR RHS A-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,000.00	1500
6	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, DOOR HINGES, RHS FRONT FENDER LINING, RHS FRONT DOOR COVER, RHS A-PILLAR, RHS A-PILLAR BRACKET AND RHS SILL PANEL.	\$ 5,000.00	1300
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 12,352.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFG 3282 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - RH <i>me</i>	1	\$	1,190.00
2	FRONT FENDER ATTACHMENT PARTS ?	1	\$	75.00
3	FRONT FENDER BRACE - RH X	1	\$	104.00
4	FRONT FENDER BRACKET - RH FRONT <i>me</i>	1	\$	63.00
5	FRONT FENDER BRACKET - RH REAR <i>me</i>	1	\$	59.00
6	FRONT FENDER CLOSING ELEMENT - RH REAR ?	1	\$	124.00
7	FRONT FENDER SEAL - RH ?	1	\$	38.00
8	FRONT WHEEL HOUSING LINER - RH <i>me</i>	1	\$	309.00
9	FRONT WHEEL SPOILER - RH X	1	\$	100.00
10	FRONT FENDER LINING - RH <i>me</i>	1	\$	206.00
11	FRONT DOOR - RH <i>me</i>	1	\$	4,645.00
12	FRONT DOOR OUTER SEAL - RH <i>me</i>	1	\$	242.00
13	BONDING AGENT <i>me</i>	1	\$	51.00
14	CLEANING SOLUTION <i>me</i>	1	\$	80.00
15	APPLICATOR <i>me</i>	1	\$	9.00
16	FRONT DOOR ATTACHMENT PARTS X	1	\$	141.00
17	FRONT DOOR CATCH - RH ?	1	\$	172.00
18	FRONT DOOR HINGE - RH UPPER / LOWER <i>me</i>	1	\$	337.00
19	FRONT DOOR INNER SEAL - RH ?	1	\$	242.00
20	FRONT DOOR COVER - RH <i>me</i>	1	\$	570.00
SUB TOTAL SPARE PARTS		:	\$	8,757.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFG 3282 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - RH X	1	\$ 370.00	
22	FRONT ROOF CHROME MOLDING - RH X	1	\$ 749.00	
23	FRONT ROOF MOLDING RETAINER - RH X	1	\$ 4.00	
24	FRONT DOOR PANEL - RH ?	1	\$ 3,121.00	
25	FRONT DOOR WIRING SET ?	1	\$ 648.00	
26	FRONT DOOR WIRING SET ?	1	\$ 666.00	
27	FRONT TYRE PRESSURE DATA PLATE ?	1	\$ 36.00	
28	FRONT DOOR SILL TRIM STRIP - RH ?	1	\$ 280.00	
29	FRONT APERTURE PANEL BRACKET - RH ?	1	\$ 76.00	
30	FRONT APERTURE PANEL PLATE - RH ?	1	\$ 54.00	
31	ACRYLIC SEALANT ?	S/N	\$ 180.00	
32	CAVITY WAX ?	S/N	\$ 140.00	
33	STONE CHIP ?	S/N	\$ 180.00	
34	METAL FILLER POWDER ?	S/N	\$ 280.00	
35	SUNDRIES ?		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 16,041.00	
TOTAL LABOUR CHARGES		:	\$ 12,352.00	
GRAND TOTAL		:	\$ 28,393.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Rashid - HP 90010068
27/03/23 @ 1645
5 days
EXCESS: TBA
REPAIR
Resy before part

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT