

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 03 Apr 2023

Preliminary Advice

Vehicle No	: SND4988L	Accident Date	: 22/03/2023
Make	: VOLKSWAGEN TOURAN	Policy No.	: SP2001983579-01
Assignment Date	: 28/03/2023	Excess	: S\$2,000.00
Date of Inspection	: 28/3/2023	Est. Duration of Repair	: 18
Inspection At	: CHIA AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,031.78
Revised Amount	:S\$	13,710.15
Check Items (Estimated)	:S\$	14,677.23
Total	:S\$	28,387.38
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	5,664.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,336.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .
Repairer able to undertake the repair within the Nett Value \$14,336.00