

利民达摩多



Jementah Motor Works

Blk 14 Defu Lane 10 #01-406
Singapore 539195
H/P : 9299 6636 Fax : 6285 7054

Date : 28-Mar-23

D.O.A : 11-Mar-23
Owner : CHAN MEI CHAN

Estimated repair cost of SGJ 23 Z Toyota Camry

Qty	Description	Amt S(\$)
	<u>List Items</u>	
1	Front headlamp -LH	\$ 3,616.84 ? Cut ✓
1	Front bumper	\$ 895.80 SCQ \$574.24
1	Front bumper lower moulding	\$ 110.85 ? X NN
1	Front bumper fog lamp	\$ 348.45 X NN
1	Front bumper lower grille	\$ 398.30 SCR ✓
1	Front bumper side retainer LH	\$ 80.15 ? BRC \$55.6
1	Front bumper PDC sensor	\$ 295.00 ? X NN
1	Front fender -LH	\$ 795.90 DT \$561.65
1	Front fender inner shield	\$ 140.60 ? X NN
1	Front fender "HYBRID" emblem	\$ 85.49 NEC \$50
1	Front wheel rim -LH	\$ 984.60 SCR \$650
1	Front wheel hub	\$ 227.01 NEC } \$339.5
1	Front wheel bearing	\$ 186.50 NEC
1	Front shock absorber	\$ x377.00 ? NN
1	Front knuckle arm	\$ 499.80 ? DMG \$386.9
1	Front lower arm	\$ 445.61 ? DMG \$288.1
1	Front door -LH	\$ 1,405.70 BUC \$1101.0
1	Front door rubber	\$ 230.50 NEC \$174.93
1	Front door side mirror	\$ 846.00 R
		7358.35\$ 11,970.10 7358.35
	Less 25%	1839.59\$ 2,992.53 1839.59
		5518.79\$ 8,977.58 5518.79

Special Nett Items

1	Front bumper clip (1 set)	\$	✓ 80.00	30	NEC
1	Front fender inner shield clip (1 set)	\$	40.00	?	XNN
1	Front tyre LH	\$	400.00	cut	100
		\$	520.00	130	

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	30	
2	To remove and refit front sensor.	\$	150.00	30	
3	To remove and refit front undercarriage.	\$	300.00	x	
4	To conduct wheel alignment.	\$	180.00		60
5	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	200.00		60
6	To apply undercoating.	\$	150.00		60
7	Panel beating.	\$	1,400.00		600
7		\$	1,200.00		600
8	To re-spray painting on the affected areas.	\$	3,660.00		1440

Grand Total :

\$ 13,157.58 ~~7343.5~~

03 days

Akid 87005631

28/03/2023 1540hrs

~~2090-1468.7~~

= \$5874.8

= \$5700

7088.79

20% = 1417.8

= 5671.00

= 5650.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: