

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0320/2023/EQ
DATE : 28-Mar-23
WIP : 13799

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/3/2023
YOUR INSURED VEH NO : XE 4126 J

Allianz Insurance Singapore Pte Ltd

79 Robinson Road

#09-01

Singapore 068897

Attn: Motor Claims Dept

OWNER'S NAME : MR NG TIONG GEE
ADDRESS : 5 TAMPINES STREET 86
#03-18
SINGAPORE 528585
TELEPHONE : HP +65 98753191
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : GA568688
VEHICLE NO : **SKT 607 P**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 31/3/2020
ENGINE NO : DLH 065519
CHASSIS NO : WAUZZZF26LN015164
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Mar-23
PLACE OF ACCIDENT : EAST COAST AVENUE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKT 607 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS FRONT DOOR.	\$ 4,000.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 8,552.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 607 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,187.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 689.00	
3	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 263.00	
4	FRONT BUMPER ADAPTER - LH / RH	2	\$ 94.00	
5	FRONT BUMPER REINFORCEMENT - RH	1	\$ 132.00	
6	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 181.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 248.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 513.00	
9	FRONT BUMPER AIR GUIDE - RH INNER	1	\$ 39.00	
10	FRONT BUMPER AIR GUIDE - RH OUTER	1	\$ 31.00	
11	RADIATOR GRILLE	1	\$ 2,603.00	
12	RADIATOR GRILLE COVER - CENTER	1	\$ 65.00	
13	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	
14	FRONT PARKING AID SEAL RING	4	\$ 11.00	
15	HORN HIGH TONE - RH	1	\$ 157.00	
16	HORN BRACKET - RH	1	\$ 56.00	
17	FRONT FENDER - RH	1	\$ 1,746.00	
18	FRONT FENDER BRACE - RH	1	\$ 146.00	
19	FRONT FENDER BRACKET - RH UPPER	1	\$ 52.00	
20	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 63.00	
SUB TOTAL SPARE PARTS		:	\$ 10,819.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 607 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS	1	\$ 89.00	
22	FRONT WHEEL HOUSING LINER	1	\$ 322.00	
23	FRONT JOINTED SHAFT COVER - RH	1	\$ 44.00	
24	FRONT WHEEL SPOILER - RH	1	\$ 196.00	
25	FRONT WHEEL SPOILER STONE CHIP GUARD - RH	1	\$ 60.00	
26	FRONT WHEEL SPOILER TRIM BRACKET - RH	1	\$ 48.00	
27	BONNET	1	\$ 5,971.00	
28	BONNET IMPACT PROTECTION - LH	1	\$ 22.00	
29	BONNET IMPACT PROTECTION - RH	1	\$ 24.00	
30	BONNET IMPACT PROTECTION - CENTER	1	\$ 53.00	
31	BONNET STRIKER	1	\$ 130.00	
32	BONNET LOCK	1	\$ 244.00	
33	HEADLIGHT MOUNTING - RH	1	\$ 140.00	
34	HEADLIGHT - RH	1	\$ 5,161.00	
35	HEADLIGHT COMPENSATING PIECE	1	\$ 48.00	
36	HEADLIGHT COMPENSATING PIECE	1	\$ 48.00	
37	HEADLIGHT HOSE - RH	1	\$ 34.00	
38	FRONT NUMBER PLATE	S/N	\$ 60.00	
39	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 23,913.00	
TOTAL LABOUR CHARGES		:	\$ 8,552.00	
GRAND TOTAL		:	\$ 32,465.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT