

AUTOMOBILE HUB

VEHICLE DETAILS

VEHICLE NO : GBJ1677P
 VEHICLE MODEL : TOYOTA DYNA
 CHASSIS NO : JTFAT35Y10K211828

2019 JAN

TP HSBC

Xiao Chun.

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	FRONT BUMPER <i>Best.</i>		692.80	✓
2	FRONT BUMPER BRACKET <i>Best.</i>		162.90	✓
3	HEADLAMP <i>lt</i>		966.70	✓
4	FRONT DOOR <i>Dented</i>		1485.40	✓
5	FRONT DOOR LOCK <i>new</i>		295.10	X.
6	FRONT DOOR WEATHERSTRIPE <i>lt</i>		228.10	✓
7	FRONT DOOR INNER TRIM BOARD <i>new</i>		698.70	X
8	FRONT DOOR HINGE @112.10 <i>1 piece Best</i>		224.20	112.10
9	FRONT DOOR CHECK <i>new</i>		131.70	X.
10	FRONT DOOR GLASS REGULATOR GEAR <i>new</i>		376.50	X
11	FRONT DOOR GLASS REGULATOR MOTOR <i>new</i>		448.90	X
12	FRONT STEP GARNISH <i>lt</i>		289.80	✓
13	FRONT WHEEL RIM MUDFLAP <i>new</i>		189.80	X
14	FRONT WHEEL ARC PANEL SIDE MOULDING <i>new</i>		119.70	X.
			3937.80	
			2953.35	
			less	
			25%	
			6310.30	
			1577.58	25%
			4732.73	
			30.00	X
			30.00	✓
			250.00	150.
			310.00	
			180	
			Total Parts	
SPECIAL NETT ITEMS				
1	FRONT DOOR INNER TRIM BOARD CLIPS <i>new</i>			
2	FRONT DOOR COMPANY ADDRESS STICKER <i>new</i>			
3	STICKERS <i>new</i>			

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
LABOUR			
1	PANEL BEATING	800.00	500.
2	SPRAY PAINTING	800.00	400
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	150.00	40
5	TO TRANSFER DOOR FITTINGS	150.00	60.
		1950.00	1030
		6992.73	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for approval
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

total: 4163.35
 H/s: 3.3K.
 04 Days.