

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 27-Mar-23

Estimate no.

1239

Plate No. FZ7608T

Model. HONDA CB400

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 1,200.00	? BT R 50	
2	FORK T-UNDER BRACKET	\$ 500.00	? BT \$265	
3	STEERING CONE	\$ 300.00	? NEC \$220	
4	FRONT DISC BRAKE SET	\$ 800.00	? BT \$679	
5	FRONT SPORT RIM	\$ 950.00	? R 50	
6	FRONT FENDER	\$ 280.00	? CRC \$145	
7	HEAD LAMP	\$ 350.00	BRC ✓	
8	HEAD LAMP STAY	\$ 250.00	? BT \$120	
9	HEAD LAMP BRACKET RIGHT	\$ 200.00	? BT \$53	
10	HEAD LAMP BRACKET LEFT	\$ 200.00	? BT \$53	
11	HEAD COVER	\$ 120.00	SCR ✓	
12	FRONT NUMBER PLATE	\$ 30.00	BT \$10	
13	FRONT SIGNAL LIGHT RIGHT	\$ 150.00	BMC \$65	
14	FRONT SIGNAL LIGHT LEFT	\$ 150.00	BMC \$65	
15	METER	\$ 950.00	BRC ✓	
16	HANDLE BAR	\$ 300.00	? BT 214	
17	HANDLE BALANCER	\$ 100.00	SCR 60	
18	CLUTH LEVER	\$ 120.00	x SCR 58	
19	BRAKE LEVER	\$ 120.00	BT 65	
20	MIRROR SET	\$ 180.00	01 Missing 95	
21	HANDLE BRACKET	\$ 280.00	? x R 50	
22	PHONE HOLDER	\$ 80.00	Missing 30	
23	CLUTH HOLDER	\$ 120.00	? BRC 62.40	
24	CLUTH CABEL	\$ 100.00	? BRC 55	
25	HORN SWITCH	\$ 180.00	x 70	
26	CRASH BAR LH	\$ 450.00	SCR 155	
27	FUEL TANK	\$ 850.00	SCR ✓	
28	REAR FAIRING COVER LH	\$ 300.00	SCR ✓	
29	REAR FOOTREST LEFT	\$ 120.00	x BT	
30	REAR FOOTREST BRACKET LEFT	\$ 220.00	x BT	

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 27-Mar-23

Estimate no. 1239

Plate No. FZ7608T

Model. HONDA CB400

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
30	FRONT FOOTREST LEFT	\$ 150.00	BT 30	
31	FRONT FOOTREST BRACKET LEFT	\$ 280.00	DT 160	
32	REAR SIGNAL LIGHT LEFT	\$ 150.00	X	
33	SPRAY COVERSET	\$ 500.00	300 350	
34	REAR SWING ARM	\$ 1,200.00	7. R BT 100 Parts	
35	REAR BOX	\$ 650.00	Missing / Parts	
36	LABOUR	\$ 800.00	450	

\$5289.4

10% = \$528.94

\$4760.46

Labour

700 / panel

3501 Spray

\$1050

Total: \$5810.46

04 days

Akid

28103123

1438hrs

8700 5631

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 1,368.00
 \$ 13,680.00
 Sub Total : \$ 12,312.00
 GST 8% \$ 984.96
 Total: \$ 13,296.96

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.