

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 27-Mar-23

Estimate no.

1239

Plate No. FZ7608T

Model. HONDA CB400

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 1,200.00	? BT R 50	
2	FORK T-UNDER BRACKET	\$ 500.00	? BT \$265	
3	STEERING CONE	\$ 300.00	? NEC \$220	
4	FRONT DISC BRAKE SET	\$ 800.00	? BTx	
5	FRONT SPORT RIM	\$ 950.00	? R 50	
6	FRONT FENDER	\$ 280.00	? CRC \$145	
7	HEAD LAMP	\$ 350.00	BRC ✓	
8	HEAD LAMP STAY	\$ 250.00	? BT \$120	
9	HEAD LAMP BRACKET RIGHT	\$ 200.00	? BT \$58	
10	HEAD LAMP BRACKET LEFT	\$ 200.00	? BT \$58	
11	HEAD COVER	\$ 120.00	SCR ✓	
12	FRONT NUMBER PLATE	\$ 30.00	BT \$10	
13	FRONT SIGNAL LIGHT RIGHT	\$ 150.00	DMC \$65	
14	FRONT SIGNAL LIGHT LEFT	\$ 150.00	DMC \$65	
15	METER	\$ 950.00	BRC ✓	
16	HANDLE BAR	\$ 300.00	? BT 214	
17	HANDLE BALANCER	\$ 100.00	SCR 60	
18	CLUTH LEVER	\$ 120.00	x SCR 58	
19	BRAKE LEVER	\$ 120.00	BT 65	
20	MIRROR SET	\$ 180.00	ol Missing 95	
21	HANDLE BRACKET	\$ 280.00	? x R 50	
22	PHONE HOLDER	\$ 80.00	Missing 30	
23	CLUTH HOLDER	\$ 120.00	? BRC 62.40	
24	CLUTH CABEL	\$ 100.00	? BRC 55	
25	HORN SWITCH	\$ 180.00	x 70	
26	CRASH BAR LH	\$ 450.00	SCR 155	
27	FUEL TANK	\$ 850.00	SCR ✓	
28	REAR FAIRING COVER LH	\$ 300.00	SCR ✓	
29	REAR FOOTREST LEFT	\$ 120.00	x DT	
30	REAR FOOTREST BRACKET LEFT	\$ 220.00	x BT	

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

ERZAT LEE MOTOR TRADING PTE LTD

REG. NO. 201918537M
EMAIL : enquiry@erzatleemotor.com
Office : 69661751

ESTIMATE COST OF REPAIR

Date: 27-Mar-23

Estimate no. 1239

Plate No. F27608T

Model. HONDA CB400

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
30	FRONT FOOTREST LEFT	\$ 150.00	BT 30	
31	FRONT FOOTREST BRACKET LEFT	\$ 280.00	DT 160	
32	REAR SIGNAL LIGHT LEFT	\$ 150.00	X	
33	SPRAY COVERSET	\$ 500.00	300 350	
34	REAR SWING ARM	\$ 1,200.00	? X	
35	REAR BOX	\$ 650.00	Missing / Parts	
36	LABOUR	\$ 800.00	450	

\$4610.4

10% = \$461.04

\$4149.36

Labour

700 / panel

350 / Spray

\$1050

Total: \$5199.36

04 days

Akid

8700 5631

28103123

1438hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 1,368.00
\$ 13,680.00
Sub Total : \$ 12,312.00
GST 8% \$ 984.96
Total: \$ 13,296.96

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.