



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: KHOR SAW THENG		Ref: CS/HSB23003196/Wvp3m4 Date: 07/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2902J	Veh. Inspected	FZ 7608T
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04K4C	Excess (\$)	0.00
Assign From	KHOR SAW THENG	Assign Date	28/03/2023
2. Vehicle Particulars & Condition			
Make & Model	HONDA CB400SF	c.c	399
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JH2NC39954M020105	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70 R17	BRIDGESTONE	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60 R17	BRIDGESTONE	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/03/2023	Inspection Date	28/03/2023
Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	