

Date: 27/03/2023

Vehicle No: SNG4711C

Model: TOYOTA PRIUS PLUS

Chassis: JTDZS3EU30J068544-2021

Reg. Year: 2022

Third Party Insurer: CHINA TAIPING

Third Party Veh No: YM7122X

Date of Accident: 25/03/2023

Estimator: TING AN

Surveyor:

NOT Withheld

11 Pgs &

Heavy Hitter Rain

2 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		Per \$549.00
2	REAR BUMPER LOWER LIP	1		Per \$726.00
3	REAR BUMPER SIDE BRACKET LH	1		P.1 \$144.00
4	REAR BUMPER REFLECTOR LH	1		Per \$75.00
5	REAR BUMPER REINFORCEMENT	1		\$205.00
SUB TOTAL				\$1,699.00
LESS 25%				-\$424.75
PARTS TOTAL				\$1,274.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		Per \$50.00
2	REAR BUMPER REVERSE SENSOR	1		Per \$300.00
S/N TOTAL				\$350.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

2000 \$300.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC.

2000 \$300.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

500 \$120.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

Per \$100.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

Per \$80.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before later spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party is on basis
- No illegal modification allowed

LABOUR TOTAL

\$900.00

TOTAL

\$2,524.25

TING AN

Head office

6 Kung Chong Road Singapore 169143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9910 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1822 | Fax: (+65) 6481 4014

