

(08/11/0) waf

SS REC. BY: [Signature]

REF:

CS/SCD 23003205/Rqy3

8354

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: SHA 8472Tat Workshop m/s DINH ANUof 31, Collaboration RD

Insured:

SCD

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

35k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 14K

Veh No:

SHA 8472T

Yr Regn:

2018 / onlyType: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make:

HYUNDAI BE 10M1Q HKV16 c.c. 1580

Colour:

YELLOW

A/C:

Insured / Std / NI / NA

Sp. Reading

351584

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH2851CVJH103740Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TRIANGLE

Front:

Rear:

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/03/23

D.O.I.

28/03/23

Survey held at

DINH ANU

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

28/03/2023 11:41

JOB-NO: 50114953

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA8472T

TRANS: AUTO

CHASSIS: KMHC851CVJU103740

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI

ENGINE: G4LEJU047975

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREAS	1.00	2,600.00	0.00	2,600.00	Y		1400
2 TO RUST PROOFING OF AFFECTED AREAS	1.00	180.00	0.00	180.00	Y		80
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	1.00	350.00	0.00	350.00	Y		X
4 TO DIAGNOSTIC, CHECK WIRING, LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	250.00	0.00	250.00	Y		150
5 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y		X
6 TO REMOVE AND REFIT REAR TAILGATE UPPER AND LOWER WINDSCREEN GLASS TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00	Y		120
7 TO REMOVE AND REFIT REAR UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR	1.00	350.00	0.00	350.00	Y		X
8 TO REMOVE AND REFIT REAR EXHAUST TO ENABLE BODYWORK REPAIR	1.00	150.00	0.00	150.00	Y		X
9 TO REFIT REAR REVERSE SENSOR	1.00	100.00	0.00	100.00	Y		40
10 TO REMOVE AND REFIT REAR BOOT MECHANISM AND PERFORM WATER SEEPAGE TEST	1.00	200.00	0.00	200.00	Y		30
11 MOUNT WORKBENCH - TO REALIGNMENT CHASSIS AND ACCIDENT AFFECTED AREA	1.00	450.00	0.00	450.00	Y		X
12 TO CHECK AND REPAIR WIRE HARNESS	1.00	240.00	0.00	240.00	Y		X
13 TO RESPRAY REAR BUMPER COVER	1.00	250.00	0.00	250.00	Y		200
14 TO RESPRAY REAR BUMPER CENTER MOULDING	1.00	250.00	0.00	250.00	Y		100
15 TO RESPRAY REAR BUMPER LOWER MOULDING	1.00	250.00	0.00	250.00	Y		100
16 TO RESPRAY REAR REVERSE SENSOR	1.00	250.00	0.00	250.00	Y		X
17 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	Y		200
18 TO RESPRAY REAR TAILGATE PANEL	1.00	250.00	0.00	250.00	Y		250
19 TO RESPRAY REAR TAILGATE SPOILER	1.00	250.00	0.00	250.00	Y		X
20 TO RESPRAY REAR RH QUARTER PANEL	1.00	250.00	0.00	250.00	Y		200
21 TO RESPRAY REAR RH DOOR PANEL	1.00	250.00	0.00	250.00	Y		200
22 TO RESPRAY REAR FLOOR PAN & EXTENSION	1.00	250.00	0.00	250.00	Y		100
23 TO RESPRAY TAILLAMP PANEL RH	1.00	250.00	0.00	250.00	Y		100
TOTAL:		8,000.00	0.00	8,000.00			

MATERIALS

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
1 REAR BUMPER <i>turn</i>	1.00	459.40	91.88	367.52	L	Y	
2 REAR RH BUMPER RETAINER <i>mis</i>	1.00	33.10	6.62	26.48	L	Y	
3 REAR BUMPER CENTER MOULDING <i>sea</i>	1.00	270.10	54.02	216.08	L	Y	
4 REAR BUMPER LOWER MOULDING <i>sea</i>	1.00	47.50	9.50	38.00	L	Y	
5 REAR BUMPER REINFORCEMENT <i>X</i>	1.00	294.80	58.96	235.84	L	Y	
6 REAR LH BUMPER REINFORCEMENT BRACKET <i>X</i>	1.00	138.10	27.62	110.48	L	Y	
7 REAR RH BUMPER REINFORCEMENT BRACKET <i>X</i>	1.00	138.10	27.62	110.48	L	Y	
8 REAR RH BUMPER UNDER COVER <i>sea</i>	1.00	35.90	7.18	28.72	L	Y	
9 REAR RH BUMPER REFLECTOR <i>sea</i>	1.00	31.90	6.38	25.52	L	Y	
10 REAR BUMPER WIRE HARNESS <i>X</i>	1.00	210.10	42.02	168.08	L	Y	
11 REAR BUMPER CENTER UNDER COVER <i>X</i>	1.00	28.70	5.74	22.96	L	Y	
12 REAR EXHAUST TAIL PIPE <i>X</i>	1.00	943.50	188.70	754.80	L	Y	
13 REAR EXHAUST HEAT SHIELD <i>X</i>	1.00	61.90	12.38	49.52	L	Y	
14 REAR EXHAUST TAIL PIPE GASKET <i>X</i>	1.00	14.10	2.82	11.28	L	Y	
15 REAR FOG LAMP ASSY <i>X</i>	1.00	201.50	40.30	161.20	L	Y	
16 SMART KEY ANTENNA <i>X</i>	1.00	40.50	8.10	32.40	L	Y	
17 REAR TAILGATE PANEL ASSY <i>bt</i>	1.00	2,480.40	496.08	1,984.32	L	Y	
18 REAR TAILGATE HYUNDAI EMBLEM <i>ne</i>	1.00	68.20	13.64	54.56	L	Y	
19 REAR TAILGATE IONIQ EMBLEM <i>ne</i>	1.00	48.20	9.64	38.56	L	Y	
20 REAR TAILGATE HYBRID EMBLEM <i>ne</i>	1.00	51.20	10.24	40.96	L	Y	
21 REAR BOOT WEATHERSTRIP <i>ne</i>	1.00	127.40	25.48	101.92	L	Y	
22 REAR BOOT LOCK <i>X</i>	1.00	224.00	44.80	179.20	L	Y	
23 BOOT REFLECTOR LAMP RH <i>cm</i>	1.00	794.40	158.88	635.52	L	Y	
24 TAILLAMP RH <i>cm</i>	1.00	905.20	181.04	724.16	L	Y	
25 TAILLAMP PANEL RH <i>buc</i>	1.00	208.90	41.78	167.12	L	Y	
26 REAR TAILGATE SPOILER <i>X</i>	1.00	665.40	133.08	532.32	L	Y	
27 REAR BOOT INNER TRIM BOARD (BIG) <i>X</i>	1.00	159.70	31.94	127.76	L	Y	
28 REAR RH LUGGAGE SIDE TRIM <i>de</i>	1.00	255.10	51.02	204.08	L	Y	
29 REAR RH LUGGAGE TRAY <i>X</i>	1.00	113.40	22.68	90.72	L	Y	
30 REAR RH QUARTER PANEL OUTER <i>buc</i>	1.00	1,768.30	353.66	1,414.64	L	Y	
31 REAR RH FENDER LINER <i>de</i>	1.00	139.10	27.82	111.28	L	Y	
32 REAR RH QUARTER PANEL AIR VENT <i>mis</i>	1.00	57.60	11.52	46.08	L	Y	
33 REAR RH BLIND SPOT COLLISION UNIT <i>cm</i>	1.00	1,874.40	374.88	1,499.52	L	Y	
34 REAR RH QUARTER PANEL INNER <i>requir</i>	1.00	1,406.20	281.24	1,124.96	L	Y	
35 REAR RH WHEEL RIM <i>requir</i>	1.00	1,091.50	218.30	873.20	L	Y	
36 REAR RH KNUCKLE ARM <i>X</i>	1.00	386.90	77.38	309.52	L	Y	
37 REAR RH KNUCKLE HUB + BEARING <i>X</i>	1.00	454.00	90.80	363.20	L	Y	
38 REAR RH LOWER ARM <i>X</i>	1.00	393.10	78.62	314.48	L	Y	
39 REAR RH UPPER ARM <i>X</i>	1.00	112.20	22.44	89.76	L	Y	
40 REAR RH ASSIST ARM <i>X</i>	1.00	92.80	18.56	74.24	L	Y	
41 REAR RH SUSPENSION SHOCK ABSORBER <i>X</i>	1.00	230.50	46.10	184.40	L	Y	
42 REAR RH STABILIZER LINK <i>X</i>	1.00	92.10	18.42	73.68	L	Y	
43 REAR SUSPENSION CROSSMEMBER <i>X</i>	1.00	756.40	151.28	605.12	L	Y	
44 REAR STABILIZER BAR <i>X</i>	1.00	224.00	44.80	179.20	L	Y	
45 REAR RH TRAILING ARM <i>X</i>	1.00	121.00	24.20	96.80	L	Y	
46 REAR END PANEL <i>bt</i>	1.00	532.00	106.40	425.60	L	Y	
47 REAR FLOOR PAN <i>X</i>	1.00	292.50	58.50	234.00	L	Y	
48 REAR RH FLOOR PAN EXTENSION <i>requir</i>	1.00	37.20	7.44	29.76	L	Y	
49 REAR END PANEL TRIM BOARD <i>X</i>	1.00	59.80	11.96	47.84	L	Y	
50 REAR RH DOOR PANEL <i>requir</i>	1.00	2,147.90	429.58	1,718.32	L	Y	
51 REAR RH FLOOR SIDE MEMBER <i>requir</i>	1.00	1,263.80	252.72	1,010.88	L	Y	
52 REAR LH TAILGATE HINGE <i>X</i>	1.00	31.30	6.26	25.04	L	Y	
53 REAR RH TAILGATE HINGE <i>X</i>	1.00	31.30	6.26	25.04	L	Y	
54 REAR LUGGAGE CENTER TRAY <i>X</i>	1.00	87.20	17.44	69.76	L	Y	
55 REAR RH PILLAR INNER TRIM <i>X</i>	1.00	38.70	7.74	30.96	L	Y	
56 REAR RH LUGGAGE TRIM UPPER COVER <i>X</i>	1.00	49.40	9.88	39.52	L	Y	
57 SPARE TYRE LOCK <i>X</i>	1.00	18.30	3.66	14.64	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
58 SPARE TYRE BOARD <i>X</i>	1.00	259.40	51.88	207.52	L	Y	X
59 REAR BUMPER CLIP SET <i>m</i>	1.00	55.00	0.00	55.00	S	Y	30
60 REAR BUMPER MOULDING CLIP <i>m</i>	1.00	50.00	0.00	50.00	S	Y	30
61 REAR REVERSE SENSOR SET <i>X</i>	2.00	300.00	0.00	300.00	S	Y	X
62 REAR TYRE 195/60/15 <i>X</i>	1.00	350.00	0.00	350.00	S	Y	X
63 REAR BUMPER ADVERTISEMENT STICKER <i>m</i>	1.00	250.00	0.00	250.00	S	Y	150
64 REAR BUMPER PROTECTOR <i>m</i>	1.00	120.00	0.00	120.00	S	Y	80
65 REAR LH QUARTER PANEL ADVERTISEMENT STICKER <i>3 m</i>	1.00	250.00	0.00	250.00	S	Y	150
66 REAR RH QUARTER PANEL ADVERTISEMENT STICKER <i>3 m</i>	1.00	250.00	0.00	250.00	S	Y	150
67 REAR QUARTER PANEL SEALANT <i>m</i>	2.00	120.00	0.00	120.00	S	Y	60 60
68 REAR END PANEL SEALANT <i>m</i>	2.00	120.00	0.00	120.00	S	Y	60 60
69 REAR WINDSCREEN SEALANT <i>m</i>	3.00	150.00	0.00	150.00	S	Y	60
70 REAR WINDSCREEN PRIMER <i>m</i>	2.00	100.00	0.00	100.00	S	Y	60
71 REAR FENDER LINER CLIP <i>m</i>	1.00	50.00	0.00	50.00	S	Y	30
72 REAR TAILGATE "6552-1111" STICKER <i>m</i>	1.00	100.00	0.00	100.00	S	Y	50
73 REAR TAILGATE "COMFORT DELGRO" STICKER <i>m</i>	1.00	100.00	0.00	100.00	S	Y	50
74 REAR TAILGATE "BOOK NOW" STICKER <i>X</i>	1.00	100.00	0.00	100.00	S	Y	X
75 REAR TAILGATE ADVERTISEMENT STICKER <i>m</i>	1.00	250.00	0.00	250.00	S	Y	150
76 TAILLAMP GUIDE CLIP SET <i>m</i>	1.00	50.00	0.00	50.00	S	Y	30
77 REAR BOOT INNER TRIM BOARD CLIP <i>m</i>	1.00	50.00	0.00	50.00	S	Y	30
78 REAR BUMPER UNDER COVER CLIP SET <i>3 m</i>	1.00	55.00	0.00	55.00	S	Y	30
79 TAILLAMP PANEL SEALANT <i>m</i>	2.00	100.00	0.00	100.00	S	Y	30
80 REAR FLOOR PAN SEALANT <i>X</i>	2.00	120.00	0.00	120.00	S	Y	X
81 REAR END PANEL SEALANT <i>X</i>	2.00	120.00	0.00	120.00	S	Y	X
82 REAR DOOR STICKER-COMFORT DELGRO LOGO RH <i>m</i>	1.00	100.00	0.00	100.00	S	Y	50
83 REAR DOOR STICKER-APP STORE & BOOK NOW RH <i>m</i>	1.00	100.00	0.00	100.00	S	Y	50
84 REAR DOOR ADVERTISEMENT STICKER <i>m</i>	1.00	250.00	0.00	250.00	S	Y	150
85 SIDE SKIRT ADVERTISEMENT STICKER <i>X</i>	1.00	250.00	0.00	250.00	S	Y	X
TOTAL:		27,009.40	6,19.88	22,389.52			
TOTAL PARTS & LABOUR:		35,009.40	4,619.88	30,389.52			

EXCESS/LOADING:\$ 0.00

No. Of Day:

*11 days*RE-SURVEY: BEFORE AFTER PAINTINGPART-BY-PART OR LUMP SUM:\$DATE OF SURVEY: *28 / 03 / 23* (*21620*)

SURVEYED BY:

Rasul

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Request for book value

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

Vehicle Details

839G

Vehicle No.:

SHA8472T

Vehicle to be Exported:

Yes

Intended Deregistration Date:

29 Mar 2023

Vehicle Make:

HYUNDAI

Vehicle Model:

AE IONIQ HEV 1.6 DCT

Primary Colour:

Yellow

Manufacturing Year:

2018

Engine No.:

G4LEJU047975

Chassis No.:

KMHC851CVJU103740

Maximum Power Output:

103.6 kW (138 bhp)

Open Market Value:

\$24,737.00

Original Registration Date:

01 Aug 2018

First Registration Date:

01 Aug 2018

Transfer Count:

0

Actual ARF Paid:

\$11,632.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

31 Jul 2026

PARF Rebate Amount:

\$8,724.00

Intended COE Rebate Details

COE Expiry Date:

31 Jul 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$27,358.00

COE Rebate Amount:

\$11,417.00

Total Rebate Amount:

\$20,141.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Mar 2023

OK