

Shiau Chan (LKKAuto)

**From:** Rasul (LKKAuto)  
**Sent:** Tuesday, 23 May 2023 12:39 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** Fw: [Finalisation] 50114953 / SHA8472T & QX2507P (DOA: 23/03/2023)

case finalised

Best Regards,  
**Rasul** | Assessor  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Taxis Customer Service <taxiscs@stengg.com>  
**Sent:** Tuesday, 23 May 2023 12:35 pm  
**To:** Rasul (LKKAuto) <Rasul@lkkauto.com>; Sarah Ong <sarah@dingautomotive.com>  
**Subject:** Re: [Finalisation] 50114953 / SHA8472T & QX2507P (DOA: 23/03/2023)

Hi All,  
  
Amount confirmed.  
  
Thanks.

---

**From:** Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Sent:** Tuesday, May 23, 2023 12:28 PM  
**To:** Sarah Ong <sarah@dingautomotive.com>  
**Cc:** Taxis Customer Service <taxiscs@stengg.com>  
**Subject:** Re: [Finalisation] 50114953 / SHA8472T & QX2507P (DOA: 23/03/2023)

**\*\*\* WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING. \*\*\***  
**Do not click on links or attachments if you are unsure of the source.**  
  
Hi Sarah,

As spoken to Loong,

We will be advising our principal a cost of repair L/S \$10,050.00 /- with 12 days of repair before GST, subject to their approval.  
  
Kindly acknowledge

Best Regards,  
**Rasul** | Assessor  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Sarah Ong <sarah@dingautomotive.com>  
**Sent:** Monday, 22 May 2023 4:41 pm  
**To:** Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Cc:** Kelly Ding <kelly@dingautomotive.com>; claims@dingautomotive.com <claims@dingautomotive.com>; Taxis Customer Service <taxiscs@stengg.com>  
**Subject:** [Finalisation] 50114953 / SHA8472T & QX2507P (DOA: 23/03/2023)

**Without Prejudice**

Dear Rasul

We understand from Loong that he had provided the price list to check for the below two parts.

Kindly verify and re-confirm the cost of repair @ **11 + 1 = 12 repair days**.

*Please Cc: [kelly@dingautomotive.com](mailto:kelly@dingautomotive.com); [claims@dingautomotive.com](mailto:claims@dingautomotive.com) in all correspondence.*

Thanks & regards,

**Sarah**  
Claims Dept.  
Ding Automotive Pte Ltd  
2 Pereira Road | #04-02, 2Connectt@TS | Singapore 368024  
T: (+65) 9239 4128 | E: [sarah@dingautomotive.com](mailto:sarah@dingautomotive.com)

On Thu, 18 May 2023 at 10:31, Taxis Customer Service <[taxiscs@stengg.com](mailto:taxiscs@stengg.com)> wrote:

Hi All,

The part number for Taillamp RH is 92402-G2100 and the part number for Blind Spot Detection Unit is 95821-G2000

Please double check on your side and reply us as soon as possible

Thanks.

---

**From:** Rasul (LKKAUTO) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Sent:** Thursday, May 18, 2023 9:34 AM  
**To:** Taxis Customer Service <[taxiscs@stengg.com](mailto:taxiscs@stengg.com)>  
**Cc:** Kelly Ding <[kelly@dingautomotive.com](mailto:kelly@dingautomotive.com)>; [sarah@dingautomotive.com](mailto:sarah@dingautomotive.com) <[sarah@dingautomotive.com](mailto:sarah@dingautomotive.com)>; [claims@dingautomotive.com](mailto:claims@dingautomotive.com) <[claims@dingautomotive.com](mailto:claims@dingautomotive.com)>  
**Subject:** Re: 50114953 / SHA8472T - Finalize Amount and After Paint Photo . (DOA: 23/03/2023)

**\*\*\* WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING. \*\*\***  
**Do not click on links or attachments if you are unsure of the source.**

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hi Sarah,

refer to attachment.

Some parts price need verification.

We will be advising our principal a cost of repair L/S \$9,950.00 /- with 11 days of repair before GST, subject to their approval.

Kindly acknowledge

*Save the Earth. Print only when necessary.*

---

**From:** Taxis Customer Service <[taxiscs@stengg.com](mailto:taxiscs@stengg.com)>  
**Sent:** Thursday, 13 April 2023 8:22 am  
**To:** Rasul (LKKAUTO) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Cc:** Kelly Ding <[kelly@dingautomotive.com](mailto:kelly@dingautomotive.com)>; [sarah@dingautomotive.com](mailto:sarah@dingautomotive.com) <[sarah@dingautomotive.com](mailto:sarah@dingautomotive.com)>; [claims@dingautomotive.com](mailto:claims@dingautomotive.com) <[claims@dingautomotive.com](mailto:claims@dingautomotive.com)>  
**Subject:** 50114953 / SHA8472T - Finalize Amount and After Paint Photo . (DOA: 23/03/2023)

#### Without Prejudice

Dear All,

Please refer below for the finalize according to our conversation to finalize for SHA8472T .

Please refer to the attached Estimate and After Paint for SHA8472T .

Lump Sum Repair

Total Repair – 12 Days

Labour = \$ 3220.00

S/N = \$ 1300.00

Parts = \$ 8150.64

L+S+P = \$ 12670.64 - 20% = \$ 10136.52

Total Finalize Amount = \$ 10136.52

Thanks!

This email is confidential and may also be privileged. If this email has been sent to you in error, please delete it immediately and notify us. Please do not copy, distribute, or disseminate part or whole of this email if you are not the intended recipient or if you have not been authorized to do so. We reserve the right, to the extent and under circumstances permitted by applicable laws, to retain, monitor, and intercept email messages to and from our systems. Thank you.<sup>7</sup>

This email is confidential and may also be privileged. If this email has been sent to you in error, please delete it immediately and notify us. Please do not copy, distribute, or disseminate part or whole of this email if you are not the intended recipient or if you have not been authorized to do so. We reserve the right, to the extent and under circumstances permitted by applicable laws, to retain, monitor, and intercept email messages to and from our systems. Thank you.

This email is confidential and may also be privileged. If this email has been sent to you in error, please delete it immediately and notify us. Please do not copy, distribute, or disseminate part or whole of this email if you are not the intended recipient or if you have not been authorized to do so. We reserve the right, to the extent and under circumstances permitted by applicable laws, to retain, monitor, and intercept email messages to and from our systems. Thank you.

---

 Virus-free. [www.avast.com](http://www.avast.com)

This email is confidential and may also be privileged. If this email has been sent to you in error, please delete it immediately and notify us. Please do not copy, distribute, or disseminate part or whole of this email if you are not the intended recipient or if you have not been authorized to do so. We reserve the right, to the extent and under circumstances permitted by applicable laws, to retain, monitor, and intercept email messages to and from our systems. Thank you.