



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNG9301U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **63884**
Reg No/Reg Date **SNG9301U / 15/09/2022**
Date In/Mileage **/ 0**
Chassis No **W1K1183842N3177683**
Engine No **28291480856064**
Make/Model **MB/CLA 180 COUPE**
Colour/Trim **021 191 Cosmos Blac/ 041 111 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	27/03/2023/ 17:05	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN								
POLICY NO/ACC DATE : SP2003907937 // 27-03-2023								
DRIVE IN/EXCESS : 27-03-2023 // TBA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB							0.10	380.00
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO								
STANDARD SETTINGS.NETT								
S BPNSUB								60.00
SUPPLY 1 PC REG. PLATE WITH HOUSING.NETT								
A BPILAB								120.00
CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT								
A BPILAB							0.07	500.00
REMOVE TO CHECK OR REPLACE RADIATOR, COOLING SYSTEM, CONDENSER WITH								
VACUUM AND RECHARGE OF REFRIGERANT.NETT								
A BPILAB								3840.00
REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER,								
FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.								
A BPIRES							0.01	5200.00
RESPRAY FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER,								
FRONT RIGHT FENDER, FRONT LEFT DOOR & FRONT RIGHT DOOR								
S BPNTOW								165.00
ACCIDENT TOWING FROM 201 HENDERSON RD B1 TO PLSC								
USING: CAR CARRIER AT BASEMENT								
REFER WO: 1317704								
M LH/F HEADLAMP					1.00	3424.13	00.00	3424.13
M RH/F HEADLAMP					1.00	3424.13	00.00	3424.13
M LH/F HEADLAMP CONTROL UNIT					1.00	588.67	00.00	588.67
M RH/F HEADLAMP CONTROL UNIT					1.00	618.10	00.00	618.10
M LH/F FFENDER					1.00	709.96	00.00	709.96
M RH/F FENDER					1.00	810.48	00.00	810.48
M LH/F FENDER BRACKET					1.00	20.58	00.00	20.58

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNG9301U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **63884**
Reg No/Reg Date **SNG9301U / 15/09/2022**
Date In/Mileage **/ 0**
Chassis No **W1K1183842N3177683**
Engine No **28291480856064**
Make/Model **MB/CLA 180 COUPE**
Colour/Trim **021 191 Cosmos Blac/ 041 111 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	27/03/2023/ 17:05	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RH/F FENDER BRACKET				1.00	20.58	00.00	20.58
M	RADIATOR GRILLE SUPPORT				1.00	212.89	00.00	212.89
M	RADIATOR GRILLE GARNISH SUPPORT				1.00	207.65	00.00	207.65
M	RADIATOR GRILLE LEFT GARNISH				1.00	58.43	00.00	58.43
M	RADIATOR GRILLE RIGHT GARNISH				1.00	63.46	00.00	63.46
M	RADIATOR GRILLE STAR				1.00	162.69	00.00	162.69
M	FRT BUMPER				1.00	1432.42	00.00	1432.42
M	LICENSE PLATE BASE				1.00	92.95	00.00	92.95
M	FRT IMPACT ABSORBER				1.00	128.58	00.00	128.58
M	CT/F BASIC CARRIER FOR BUMPER				1.00	130.75	00.00	130.75
M	LH/F TOP BASIC CARRIER FOR BUMPER				1.00	75.68	00.00	75.68
M	RH/F TOP BASIC CARRIER FOR BUMPER				1.00	74.64	00.00	74.64
M	LH/F BASIC CARRIER FOR BUMPER				1.00	66.79	00.00	66.79
M	RH/F BASIC CARRIER FOR BUMPER				1.00	73.45	00.00	73.45
M	FRT TOP AIR DUCT SEGMENT				1.00	133.82	00.00	133.82
M	FRT BOTTOM AIR DUCT SEGMENT				1.00	94.81	00.00	94.81
M	LH/F BUMPER BRACKET				1.00	18.35	00.00	18.35
M	RH/F BUMPER BRACKET				1.00	18.35	00.00	18.35
M	FRT RADAR SENSOR				1.00	1233.72	00.00	1233.72
M	FRT RADAR SENSOR BRACKET				1.00	24.66	00.00	24.66
M	CT/F PARKING SENSOR				4.00	205.45	00.00	821.80
M	FRT PARKING SENSOR SEAL				4.00	7.85	00.00	31.40
M	FRT PARKING SENSOR WIRING HARNESS				1.00	103.45	00.00	103.45
M	FRT PRESSURE SENSOR				1.00	197.06	00.00	197.06
M	BONNET				1.00	2098.46	00.00	2098.46
M	BONNET LEFT HINGE				1.00	89.22	00.00	89.22
M	BONNET RIGHT HINGE				1.00	89.22	00.00	89.22
M	BONNET UPPER CATCH				1.00	54.66	00.00	54.66
M	BONNET LOWER CATCH				1.00	169.32	00.00	169.32
M	BONNET LIMIT SWITCH				1.00	124.09	00.00	124.09
M	BONNET ACTUATOR				2.00	221.78	00.00	443.56
M	FRT CROSS MEMBER				1.00	442.50	00.00	442.50
M	FRT END SUPPORT MEMBER				1.00	713.10	00.00	713.10

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNG9301U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **63884**
Reg No/Reg Date **SNG9301U / 15/09/2022**
Date In/Mileage **/ 0**
Chassis No **W1K1183842N3177683**
Engine No **28291480856064**
Make/Model **MB/CLA 180 COUPE**
Colour/Trim **021 191 Cosmos Blac/ 041 111 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	27/03/2023/ 17:05	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	FRT RIGHT TOP AIR DUCT				1.00	50.11	00.00	50.11
M	CONDENSER				1.00	1171.74	00.00	1171.74
M	REFRIGERANT DRIER				1.00	288.38	00.00	288.38
M	RADIATOR				1.00	1280.78	00.00	1280.78
M	INTERCOOLER				1.00	1454.47	00.00	1454.47

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

8% GST on **Nett 33,809.04**
33809.04 **2704.72**
Total Payable 36,513.76

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG