

(D6/1103) Wef
SS. REC. BY: Rome

REF: CC3/AIS23003207/Rnp3

C
7782

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNK 9301U

at Workshop m/s Cycle & Carriage

of 188, Pannan Loop
Insured: AKS

Policy No.

Claims No.

Sum Insured:

Excess:


TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

183K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Repair Limit - 77K

Veh No:

SNK 9301U

Yr Regn:

2022/86P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ CLA 180 C c.c 1332

Colour

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

18662

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WIK1183842N317768

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / 8 Rim / STD A/Rim or

Tyre Size:

F:

225/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front:

Rear:

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/03/23

D.O.I.

28/03/23

Survey held at

C8C (PL)

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) : S + RS : SI

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNG9301U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 63884
Reg No/Reg Date SNG9301U / 15/09/2022
Date In/Mileage / 0
Chassis No W1K1183842N3177683
Engine No 28291480856064
Make/Model MB/CLA 180 COUPE
Colour/Trim 021 191 Cosmos Blac/ 041 111 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	27/03/2023/ 17:05	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : SP2008907937 // 27-03-2023

DRIVE IN/EXCESS : 27-03-2023 // TBA

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

S BPNSUB

SUPPLY 1 PC REG. PLATE WITH HOUSING.NETT

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT

A BPILAB

REMOVE TO CHECK OR REPLACE RADIATOR, COOLING SYSTEM, CONDENSER WITH
VACUUM AND RECHARGE OF REFRIGERANT.NETT

A BPILAB

REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER,
FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER,
FRONT RIGHT FENDER, FRONT LEFT DOOR & FRONT RIGHT DOOR

S BPNTOW

ACCIDENT TOWING FROM 201 HENDERSON RD B1 TO PLSC

USING: CAR CARRIER AT BASEMENT

REFER WO: 1317704

M LH/F HEADLAMP

M RH/F HEADLAMP

M LH/F HEADLAMP CONTROL UNIT

M RH/F HEADLAMP CONTROL UNIT

M LH/F FENDER

M RH/F FENDER

M LH/F FENDER BRACKET

1.00	3424.13	00.00	3424.13
1.00	3424.13	00.00	3424.13
1.00	588.67	00.00	588.67
1.00	618.10	00.00	618.10
1.00	709.96	00.00	709.96
1.00	810.48	00.00	810.48
1.00	20.58	00.00	20.58

380.00

60.00

120.00

500.00

2880 3848.00

4800 5208.00

165.00

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6270 5282



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNG9301U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **63884**
Reg No/Reg Date **SNG9301U / 15/09/2022**
Date In/Mileage **0**
Chassis No **W1K1183842N3177683**
Engine No **28291480856064**
Make/Model **MB/CLA 180 COUPE**
Colour/Trim **021 191 Cosmos Blac/ 041 111 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WA000001	Credit	27/03/2023/ 17:05	AQ	305 / Alan Quek Ai Lun					
					M RH/E FENDER BRACKET	1.00	20.58	00.00	20.58
					M RADIATOR GRILLE SUPPORT	1.00	212.89	00.00	212.89
					M RADIATOR GRILLE GARNISH SUPPORT	1.00	207.65	00.00	207.65
					M RADIATOR GRILLE LEFT GARNISH	1.00	58.43	00.00	58.43
					M RADIATOR GRILLE RIGHT GARNISH	1.00	63.46	00.00	63.46
					M RADIATOR GRILLE STARNIS	1.00	162.69	00.00	162.69
					M FRT BUMPER	1.00	1432.42	00.00	1432.42
					M LICENSE PLATE BASE	1.00	92.95	00.00	92.95
					M FRT IMPACT ABSORBER	1.00	128.58	00.00	128.58
					M CT/F BASIC CARRIER FOR BUMPER	1.00	130.75	00.00	130.75
					M LH/F TOP BASIC CARRIER FOR BUMPER	1.00	75.68	00.00	75.68
					M RH/F TOP BASIC CARRIER FOR BUMPER	1.00	74.64	00.00	74.64
					M LH/F BASIC CARRIER FOR BUMPER	1.00	66.79	00.00	66.79
					M RH/F BASIC CARRIER FOR BUMPER	1.00	73.45	00.00	73.45
					M FRT TOP AIR DUCT SEGMENT	1.00	133.82	00.00	133.82
					M FRT BOTTOM AIR DUCT SEGMENT	1.00	94.81	00.00	94.81
					M LH/F BUMPER BRACKET	1.00	18.35	00.00	18.35
					M RH/F BUMPER BRACKET	1.00	18.35	00.00	18.35
					M FRT RADAR SENSOR	1.00	1233.72	00.00	1233.72
					M FRT RADAR SENSOR BRACKET	1.00	24.66	00.00	24.66
					M CT/F PARKING SENSOR	4.00	205.45	00.00	821.80
					M FRT PARKING SENSOR SEAL	4.00	7.85	00.00	31.40
					M FRT PARKING SENSOR WIRING HARNESS	1.00	103.45	00.00	103.45
					M FRT PRESSURE SENSOR	1.00	197.06	00.00	197.06
					M BONNET	1.00	2098.46	00.00	2098.46
					M BONNET LEFT HINGE	1.00	89.22	00.00	89.22
					M BONNET RIGHT HINGE	1.00	89.22	00.00	89.22
					M BONNET UPPER CATCH	1.00	54.66	00.00	54.66
					M BONNET LOWER CATCH	1.00	169.32	00.00	169.32
					M BONNET LIMIT SWITCH	1.00	124.09	00.00	124.09
					M BONNET ACTUATOR	2.00	221.78	00.00	443.56
					M FRT CROSS MEMBER	1.00	442.50	00.00	442.50
					M FRT END SUPPORT MEMBER	1.00	713.10	00.00	713.10

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNG9301U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No **63884**
Reg No/Reg Date **SNG9301U / 15/09/2022**
Date In/Mileage **0**
Chassis No **W1K1183842N3177683**
Engine No **28291480856064**
Make/Model **MB/CLA 180 COUPE**
Colour/Trim **021 191 Cosmos Blac/ 041 111 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WA000001	Credit	27/03/2023/ 17:05	AQ	305 / Alan Quek Ai Lun					
					M FRT RIGHT TOP AIR DUCT ?	1.00	50.11	00.00	50.11
					M CONDENSER ?	1.00	1171.74	00.00	1171.74
					M REFRIGERANT DRIER ?	1.00	288.38	00.00	288.38
					M RADIATOR ?	1.00	1280.78	00.00	1280.78
					M INTERCOOLER ?	1.00	1454.47	00.00	1454.47

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

RASUL
HP 900/2068
8 days
28/03/27 @ 1410
EXECS: TBA
REVERS
Resy before paint

Confirmed & accepted by

Authorized signatory and company stamp

Nett	33,809.04
8% GST on	33809.04
Total Payable	36,513.76

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	778Z
Vehicle No.:	5NG9301U
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 COUPE PROGRESSIVE
Primary Colour:	Black
Manufacturing Year:	2022
Engine No.:	28291480856064
Chassis No.:	W1K1183842N317768
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$33,792.00
Original Registration Date:	15 Sep 2022
First Registration Date:	15 Sep 2022
Transfer Count:	0
Actual ARF Paid:	\$39,309.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2032
PARF Rebate Amount:	\$29,481.00
COE Expiry Date:	14 Sep 2032
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$80,000.00
COE Rebate Amount:	\$75,687.00
Total Rebate Amount:	\$105,168.00

The information contained herein is correct as at 29 Mar 2023

OK

Mercedes-Benz CLA-Class CLA180 Progressive

Overview

Insurance

Financial

Accessories

Similar

Research

Photos



The new automotive experience

Price	\$183,800		
Depreciation ?	\$17,310 /yr View models with similar depre	Reg Date	20-Sep-2022 (9yrs 5mths 21days COE left)
Mileage	17,000 km	Manufactured ?	2022
Road Tax ?	\$586 /yr	Transmission	Auto
Dereg Value ?	\$100,608 as of today (change)	OMV ?	\$33,792
COE ?	\$74,989	ARF ?	\$39,309
Engine Cap	1,332 cc	Power	96.0 kW (128 bhp)
Curb Weight ?	1,410 kg	No. of Owners ?	1