



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23003209/Rny3e2	
			Date: 15/05/2023	
			Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 6744L	Veh. Inspected	FBE 9791R
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS23/1041	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	28/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA NMAX 155 ABS CVT	c.c	155
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	MH3SG5680LK044163	Colour	BLACK
	Odometer	7152 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70-13	IRC	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70-13	IRC	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/03/2023	Inspection Date	28/03/2023
	Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762		
5a. Remarks				
	A)REGISTRATION DATE: 20 NOV 2020 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	