



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 27/03/2023

Attn: The Motor Claims Department
Your Insured Vehicle - YQ 5519 C

Hui Rong

Sompo Insurance Singapore Pte Ltd
50 Raffles Place,
#05-01/06, Singapore Land Tower
Singapore 048623
Tel: 6221 2211
Fax: 6221 3147

Wst: 1630
Lns 15%: 1385.50
S-N: 3200
Labours: 1730
Total: 6315.50

Estimated Cost of repair for No. for ISUZU YQ 1642 E & YQ 5519 C ON 23/03/2023 AT 08:00:00
To Supply:-

H/S: 5050

1pc	Tail Gate	Warpred			900.00	✓
5pcs	Wooden Beam	4 pillars cracked	650.00	450	3,250.00	1800 (SN)
2pcs	Canopy Pillar	Best	800.00		1,600.00	900 (SN)
1pc	Rear Fender LH	Delend	450.00		450.00	✓
1pc	Rear Lamp LH	cracked			147.00	✓
1pc	Tail Gate Bracket	But			98.00	✓
2pcs	Wooden Canopy	Smashed	450.00		900.00	500 (SN)
1set	Floor Board	we mv			1,800.00	x
1pc	Sticker	new			35.00	✓
					9,180.00	
			less	15%	- 1,377.00	
					7,803.00	

To dismantl & replace damage parts, panel beat where necessary
To putty, apply primer & spray paint on the affected portion.
To check wiring functions.

2,000.00 1200
850.00 500
120.00 30
10,773.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lim
1/s 29/03/23.
07 Days