



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 3364Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT COVER	DENTED	2,265.00	1,978.40
2	REAR BOOT HINGE LR @\$42.00	NOT NECESSARY	84.00	-
1	WIPER MOTOR	DAMAGED / JAMMED	254.00	254.00
1	WIPER ARM	SERVICEABLE	165.00	-
1	REAR BOOT LOCK	DAMAGED	331.00	260.60
1	REAR BUMPER	DEFORMED	561.00	561.00
1	REAR BOOT RUBBER	TWISTED	113.00	113.00
2	REAR LAMP LR @\$291.10	NOT NECESSARY	582.20	-
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	665.00	-
1	REAR END PANEL OUTER	DENTED / BENT	132.00	132.00
1	NISSAN LOGO	NECESSARY	74.90	74.90
1	REVERSE SENSOR	SHORTED	200.00	200.00
1	REAR BUMPER SPONGE	TORN	162.00	162.00
1	TAILGATE OUTER HANDLE	GRAZED	281.00	281.00
	LESS 10% DISCOUNT		-587.01	-401.69
			5,283.09	3,615.21
1	70KM STICKER (SN)	NECESSARY	15.00	10.00
1	6 PAX STICKER (SN)	NECESSARY	15.00	10.00
1	REAR NUMBER PLATE WITH HOUSING (SN)	SCRATCHED	60.00	40.00
1	REAR WIND SCREEN SEALANT (SN)	NECESSARY	100.00	40.00
	LESS 10% DISCOUNT		-19.00	-
			171.00	100.00
	<u>LABOUR</u>			
	TO PROVIDE PANEL KNOCKING & REPLACE ACC. INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER.		980.00	600.00
	TO PROVIDE SPRAY PAINTING AN ACC PAIDS.		800.00	500.00
	CHECK WIRING.		80.00	20.00

Report Ref No. CS/FCI23003211/Uwy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REINSTANT REAR WIND SCREEN.		160.00	100.00
			2,020.00	1,220.00
GRAND TOTAL			7,474.09	4,935.21
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CS/FCI23003211/Uwy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.