

ASS. REC. BY:

REF:

GRB/ 23003216/Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STD 5471B

Yr Regn:

03, 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 335i

c.c.

2979

Colour:

n. Black

A/C: Insured / Std / NI / NA

Sp. Reading

105534

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAWL 72010JZ 96424

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / RIM or

Tyre Size:

F:

225/40 ER18

R:

255/35 ER18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / (PIR) SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

4

mm

L/Bal.

8

mm

L/Bal.

4

mm

D.O.A.

28/3/23

D.O.I.

5/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rt O/S & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Wlcrp said unable to lump Rm, as till date still unable to locate 2nd party

6/6 @ 12,594.74

21/6 @ 13,714.00 Cash

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

SIN AUTO PTE LTD

76, Sin Ming Dr, #04-06 Sin Ming AutoCare, Singapore, Singapore,
Singapore - 575721.

Contact: +65 9231 3123

mail: desmond@insurlogic.co

Customer Name: Robert Ian Cohen
Mobile No: +65 91140884, +65 91140884

Proforma Invoice No:

Date: Mar 31 2023

Ticket No: DAP-J000007

Vehicle No: SJD5471B

Engine No: WBAWL72010JZ96424

Vehicle: BMW 3-SERIES 325I 2008

Kilometer: 105534

Color: WHITE

Fuel: PETROL

PH: +65 91140884, +65 91140884

Email: robert_i_cohen@outlook.com

Part Name	Description	Quantity	Unit Price	Taxable	Parts Total
FRONT BUMPER AR101304-05458 (1) \$1,200.00	Part	1.00	1,265.00	1,265.00	1,265.00
BONNET HOOD ASSY AR101304-05458 (4) \$1,375.00	Part	1.00	1,375.00	1,375.00	1,375.00
HINGE, BONNET/HOOD (RH)	Part	1.00	71.50	71.50	71.50
HINGE, BONNET/HOOD (LH)	Part	1.00	71.50	71.50	71.50
RADIATOR ASSY	Part	1.00	902.00	902.00	902.00
BALL JOINT, STEERING (RH) AR101304-05458 (17) \$242.00	Part	1.00	242.00	242.00	242.00
ADLAMP ASSY LH	Part	1.00	2,860.00	2,860.00	2,860.00
FRONT SHOCK ABSORBER RH AR101304-05458 (11) \$605.00	Part	1.00	605.00	605.00	605.00
ARM, LOWER CONTROL (LOWER, RH) AR101304-05446 (3) \$286.00	Part	1.00	286.00	286.00	286.00
LINK, STABILIZER (RH)	Part	1.00	198.00	198.00	198.00
STABILIZER BAR (FR)	Part	1.00	506.00	506.00	506.00
SENSOR, WHEEL SPEED/ABS (FR, RH)	Part	1.00	280.50	280.50	280.50
END, TIE ROD (RH)	Part	1.00	264.00	264.00	264.00
WHEEL ALIGNMENT 9579-04356 \$100.00	Part	1.00	100.00	100.00	100.00
FRONT BUMPER TOW CAP CORNER WITH BUMPER	Part	1.00	55.00	55.00	55.00
BONNET BADGE AR101304-05458 (1) \$82.50	Part	1.00	82.50	82.50	82.50
FRONT LOWER GRILLE AR101304-08193 (1) \$88.00	Part	1.00	88.00	88.00	88.00
HEADLAMP ASSY RH AR101304-05458 (5) \$2,860.00	Part	1.00	2,860.00	2,860.00	2,860.00
HEADLAMP PANEL RH	Part	1.00	748.00	748.00	748.00
HEADLAMP BRACKET RH AR101304-05458 (6) \$82.50	Part	1.00	82.50	82.50	82.50
FOG LAMP ASSY RH AR101304-05458 (7) \$385.00	Part	1.00	385.00	385.00	385.00
FOG LAMP BRACKET RH AR101304-05446 (1) \$110.00	Part	1.00	110.00	110.00	110.00
FRONT FENDER RH AR101304-05446 (1) \$935.00	Part	1.00	935.00	935.00	935.00
SENSOR ASSY	Part	1.00	1,265.00	1,265.00	1,265.00
WASHER TANK	Part	1.00	132.00	132.00	132.00
WHEEL KNUCKLE RH AR101304-05458 (14) \$572.00	Part	1.00	572.00	572.00	572.00
WHEEL BEARING HUB AR101304-05458 (15) \$583.00	Part	1.00	583.00	583.00	583.00
BRAKE HOSE RH	Part	1.00	187.00	187.00	187.00
ENGINE LOWER COVER AR101304-05458 (16) \$467.50	Part	1.00	467.50	467.50	467.50
AIR DUCT RH AR101304-05446 (5) \$236.50	Part	1.00	236.50	236.50	236.50
FRONT BUMPER RETAINER RH AR101304-05458 (2) \$66.00	Part	1.00	66.00	66.00	66.00
FRONT BUMPER SIDE GARNISH RH DUPLICATE ITEM	Part	1.00	88.00	88.00	88.00
FRONT BUMPER LOWER LIP GARNISH	Part	1.00	220.00	220.00	220.00
FRONT BUMPER LOWER GRILLE GARNISH	Part	1.00	93.50	93.50	93.50
FRONT BUMPER NUMBER PLATE REINF	Part	1.00	22.00	22.00	22.00
FRONT BUMPER NOZZLE COVER RH	Part	1.00	55.00	55.00	55.00
FRONT BUMPER NOZZLE JET RH	Part	1.00	181.50	181.50	181.50

BONNET LOCK RH	Part	1.00	137.50	R	137.50	X	137.50
BONNET LOCK LH	Part	1.00	137.50	R	137.50	X	137.50
BONNET LOCK BRACKET RH	Part	1.00	33.00	R	33.00	X	33.00
BONNET LOCK BRACKET LH	Part	1.00	33.00	R	33.00	X	33.00
FRONT AIR GRILLE RH	Part	1.00	198.00	R	198.00	X	198.00
FRONT AIR GRILLE LH	Part	1.00	198.00	R	198.00	X	198.00
FRONT SUPPORT PANEL CPL	Part	1.00	792.00	R	792.00	X	792.00
FRONT AIR VENT MOULDING CPL	Part	1.00	225.50	R	225.50	X	225.50
FRONT CROSS BRACE RH	Part	1.00	66.00	R	66.00	X	66.00
FRONT CROSS BRACE LH	Part	1.00	66.00	R	66.00	X	66.00
FRONT FENDER INNER SHIELD RH AR101304-05458 (819)	Part	1.00	275.00	R	275.00	X	275.00
PARKING SENSOR RH	Part	1.00	275.00	R	275.00	X	275.00
RADIATOR AIR GUIDE RH NO CHANGE	Part	1.00	93.50	R	93.50	X	93.50
RADIATOR AIR GUIDE LH	Part	1.00	93.50	R	93.50	X	93.50
INTERCOOLER - POWER STEERING AR101304-05654(1) \$650.00	Part	1.00	924.00	R	924.00	X	924.00
WASHER TANK PUMP	Part	1.00	203.50	R	203.50	X	203.50
HORN - HIGH PITCH RH	Part	1.00	82.50	R	82.50	X	82.50
ABSORBER MOUNTING RH AR101304-05458(12) \$220.00	Part	1.00	242.00	R	242.00	X	242.00
ABSORBER LINKAGE RH AR101304-05458(13) \$100.00	Part	1.00	104.50	R	104.50	X	104.50
SHOCKER RACK CPL	Part	1.00	3,135.00	R	3,135.00	X	3,135.00
ENGINE LOWER SIDE COVER RH NO CHANGE	Part	1.00	192.50	R	192.50	X	192.50
FRONT ALLOY RIM RH	Part	1.00	1,320.00	R	1,320.00	X	1,320.00
BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	Part	1.00	1,200.00	R	1,200.00	X	1,200.00
REFILL - RADIATOR COOLANT	Part	1.00	100.00	R	100.00	X	100.00
REFILL - AIR COND GAS	Part	1.00	100.00	R	100.00	X	100.00
SPRAY PAINT - FRT BUMPER, FRT FENDER RH, FRT DOOR RH, BONNET & SUPPORT PANEL	Part	1.00	1,400.00	R	1,400.00	X	1,400.00
REMOVE & REFIT - UNDERCARRIAGE COMPONENTS	Part	1.00	350.00	R	350.00	X	350.00
ALIGN HEADLAMP/FOG LAMP/PARKING SENSOR & TEST WIRING	Part	1.00	150.00	R	150.00	X	150.00
HEADLAMP MODULE - DIAGNOSIS & RE-PROGRAMMING	Part	1.00	450.00	R	450.00	X	450.00
FRT GRILLE, FRT BUMPER, INNER SHIELD, GARNISH - CLIPS	Part	1.00	200.00	R	200.00	X	200.00
FRONT NUMBER PLATE & FRAME	Part	1.00	45.00	R	45.00	X	45.00

Taxable Value
31,364.00
Discount Total 0.00
Grand Total
31,364.00

Parts Total 31,364.00
Labour Total 0.00
GST Total 0.00
Grand Total 31,364.00
Balance 31,364.00

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Supp

1) Front Thrust Arm RHS 170.00 ✓ RT

2) Oil cooler Air duct RHS 320.00 ✓ CRA

Parts \$10770.00

108 1077.00

11847.00

Labour 1680.00

Supp

13,527.00 + 187 = 13,714.00