

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 05 Apr 2023

Preliminary Advice

Vehicle No	: EY882E	Accident Date	: 21/03/2023
Make	: AUDI A6 DESIGN	Policy No.	: SP2001308983
Assignment Date	: 28/03/2023	Excess	: S\$700.00
Date of Inspection	: 05/04/2023	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOCARE CENTRE (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,819.00
Revised Amount	:S\$	3,369.00
Check Items (Estimated)	:S\$	6,193.00
Total	:S\$	9,562.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	167,000.00
COE / PARF Rebate	:S\$	62,312.00
Salvage Value	:S\$	
Margin for Repair	:S\$	104,688.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :part by part repair as repairer is agent workshop.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.