

# PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

|            |   |                      |
|------------|---|----------------------|
| ESTIMATE   | : | ACCIDENT REPAIRS     |
| WORKSHOP   | : | 24 BENOI SECTOR      |
| CONTACT NO | : | 6474 3323            |
| FAX NO     | : | 6264 6786            |
| REFERENCE  | : | PAC/OD/0034/2023/CCS |
| DATE       | : | 25-Mar-23            |
| WIP        | : |                      |

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

## ALLIANZ INSURANCE SINGAPORE PTE LTD

79 Robinson Road

#09-01

Singapore 068897

## ATTN: MOTOR CLAIMS DEPT

Tel: 6297 2529 Fax: 6297 1956

|                   |   |                                     |
|-------------------|---|-------------------------------------|
| OWNER'S NAME      | : | MR YAP YONG YAN                     |
| ADDRESS           | : | 46, GARLICK AVE<br>SINGAPORE 279665 |
| TELEPHONE         | : | HP +65 96312992                     |
| TYPE OF CLAIM     | : | OWN DAMAGE CLAIM                    |
| POLICY NO         | : | SP2002073327                        |
| VEHICLE NO        | : | EY 882 E                            |
| MODEL CODE        | : | AUDI A6 SEDAN 2.0 TFSI              |
| MODEL YEAR        | : | 27/3/2020                           |
| ENGINE NO         | : | DKY005081                           |
| CHASSIS NO        | : | WAUZZZF26LN030019                   |
| MILEAGE           | : | -                                   |
| DATE IN           | : |                                     |
| ESTIMATED BY      | : | ALLAN WU                            |
| ACCIDENT DATE     | : | 21-Mar-23                           |
| PLACE OF ACCIDENT | : | ALONG PIE, SLIP RD FROM             |



## PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857  
TEL : 6474 3323 FAX : 6264 6786  
EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE EY 882 E

| S/N                  | NATURE OF JOBS                                                                                                                                   |     | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|-----|-------------------|----------------------------|
| 1                    | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N | \$ 150.00 ✓       |                            |
| 2                    | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                           | S/N | \$ 200.00 X NA    |                            |
| 3                    | TO DISMANTLE AND RENEW FRONT BUMPER, AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.                   |     | \$ 500.00 ✓ 200   |                            |
| 4                    | TO RESPRAY FRONT BUMPER.                                                                                                                         |     | \$ 400.00 ✓ 200   |                            |
| 5                    | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                   | S/N | \$ 150.00 ✓ NECC  |                            |
| TOTAL LABOUR CHARGES |                                                                                                                                                  |     | :                 | \$ 1,400.00                |

REPAIR 3 DAYS

- NOT AUTHORISE

- EXCESS \$700

- P/P OR 1/S REPAIR

- SURVEY BY EDWARD TEL 62563561

- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# **PREMIUM AUTOCARE**

24 BENOI SECTOR, SINGAPORE 629857  
 TEL : 6474 3323 FAX : 6264 6786  
 EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EY 882 E**

| S/N PARTS DESCRIPTION                     | QTY | DAMAGED PARTS & PRICES |                  | REMARKS     |
|-------------------------------------------|-----|------------------------|------------------|-------------|
|                                           |     |                        | S/NETT           |             |
|                                           |     |                        |                  | COST + 10 % |
| 1 FRONT BUMPER                            | 1   | \$                     | 3,187.00         | R           |
| 2 FRONT BUMPER FIXING PARTS               | 1   | \$                     | 689.00           | ?           |
| 3 FRONT BUMPER CLOSING ELEMENT - CENTER   | 1   | \$                     | 263.00           | ?           |
| 4 FRONT BUMPER ADAPTER - LH/RH            | 2   | \$                     | 94.00            | ?           |
| 5 FRONT BUMPER REINFORCEMENT BEAM - LH/RH | 2   | \$                     | 264.00           | ?           |
| 6 FRONT BUMPER GRILLE - LOWER CENTRE      | 1   | \$                     | 181.00           | X NH        |
| 7 FRONT BUMPER CLOSING ELEMENT            | 1   | \$                     | 248.00           | ?           |
| 8 FRONT AIR GUIDE GRILLE - LH/RH          | 2   | \$                     | 1,026.00         | X NH        |
| 9 RADIATOR GRILLE                         | 1   | \$                     | 2,603.00         | CRA         |
| 10 RADIATOR GRILLE COVER                  | 1   | \$                     | 65.00            | ?           |
| 11 RADIATOR GRILLE CAP                    | 1   | \$                     | 59.00            | ?           |
| 12 RADIATOR GRILLE BRACKET                | 1   | \$                     | 111.00           | ?           |
| 13 FRONT CAMERA FOR PARKING ASSIST        | 1   | \$                     | 1,115.00         | ?           |
| 14 ADAPTER CABLE FOR CAMERA               | 1   | \$                     | 464.00           | ?           |
| 15 FOAM FILLER PIECE                      | 1   | \$                     | 267.00           | ?           |
| 16 FRONT REINFORCMENT BEAM                | 1   | \$                     | 1,140.00         | ?           |
| 17 FRONT BUMPER SUPPORT-LH/RH             | 2   | \$                     | 71.00            | ?           |
| 18 POP RIVET                              | 6   | \$                     | 6.00             | NEC         |
| 19 FRONT BUMPER GUIDE SECTION - LH/RH     | 2   | \$                     | 106.00           | ?           |
| 20 FRONT BUMPER COVER                     | 1   | \$                     | 149.00           | X NH        |
| <b>SUB-TOTAL PARTS CHARGES</b>            | :   | \$                     | <b>12,108.00</b> |             |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.

# **PREMIUM AUTOCARE**

24 BENOI SECTOR, SINGAPORE 629857  
 TEL : 6474 3323 FAX : 6264 6786  
 EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EY 882 E**

| S/N PARTS DESCRIPTION                                 | QTY | DAMAGED PARTS & PRICES |                  | REMARKS     |
|-------------------------------------------------------|-----|------------------------|------------------|-------------|
|                                                       |     | S/NETT                 |                  |             |
|                                                       |     |                        |                  | COST + 10 % |
| 21 STICKER FOR " SIGN CAUTION "                       | 1   | \$                     | 17.00            | X NAI       |
| 22 PARKING AID SENSOR 5                               | 2   | \$                     | 598.00           | X NAI       |
| 23 PARKING AID SENSOR SEAL RING                       | 4   | \$                     | 11.00            | ?           |
| 24 FRONT BUMPER WIRING                                | 1   | \$                     | 648.00           | ?           |
| 25 LED HEADLIGHT MOUNTING - LH/RH 21                  | 2   | \$                     | 280.00           | X NAI       |
| 26 LED HEADLIGHT - LH/RH                              | 2   | \$                     | 19,424.00        | X NAI       |
| 27 LIFT CLYLINDER FOR HEADLIGHT WASHER SYSTEM - LH/RH | 2   | \$                     | 460.00           | X NAI       |
| 28 HOSE FOR HEADLIGHT WASHER SYSTEM                   | 1   | \$                     | 208.00           | X NAI       |
| 29 TEMPERATURE SENSOR BRACKET                         | 1   | \$                     | 27.00            | X NAI       |
| 30 RADIATOR AIR GUIDE - LH/RH                         | 2   | \$                     | 100.00           | ?           |
| 31 RADIATOR AIR GUIDE - UPPER/LOWER                   | 2   | \$                     | 78.00            | ?           |
| 32 FRONT NO. PLATE 1                                  | S/N | \$                     | 60.00            | BT          |
| 33 SUNDRIES                                           |     | \$                     | 400.00           | ?           |
| <b>TOTAL PARTS CHARGES</b>                            | :   | \$                     | <b>34,419.00</b> |             |
| <b>TOTAL LABOUR CHARGES</b>                           | :   | \$                     | <b>1,400.00</b>  |             |
| <b>GRAND TOTAL</b>                                    | :   | \$                     | <b>35,819.00</b> |             |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857

TEL : 6474 3323 FAX : 6264 6786

EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6474 3323 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOCARE CENTRE

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

26257