## CITYCAB PTE LTD

## **REPAIR ESTIMATE\***

**VEHICLE NO** 

SHB2337K

MAKE

REG. 21.08.2018

MODEL

**IONIQ G2** 

18.03.2023

CHIANG/ CHINA

Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	FRONT BUMPER? - NIV			\$481.10
1	FRONT BUMPER BRACKET TOP RH ? XM		\$35.00	\$350.00
10	FRONT BUMPER CLIPS?		\$2.20	\$22.00
10	FRONT BUMPER MOULDING ?X/W			\$368.50
	FRONT RADIATOR GRILLE GOV			\$1,409.10
	SUB TOTAL			\$2,630.70
	20.00%	U .	1127.28	\$526.14
	DISCOUNTED TOTAL		1127.28	\$2,104.56
				455.00
	FRONT NUMBER PLATE?			\$55.00 <b>\$55.00</b>
	Labour Charge			4
	Panel Beating		1	\$600.00
	Spray Painting Charge			\$60.00
	Check Wiring			\$60.00
	Tuff kote	1	1	\$1,020.00
	TOTAL LABOUR			\$1,020.00
	ESTIMATE TOTAL		1477.28	\$3,179.56
		20	1477.28	
	This is an initial estimate based on a visual inspection of the		and the second second	ntum will

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.