## CITYCAB PTE LTD

## **REPAIR ESTIMATE\***

**VEHICLE NO** 

SHB2337K

MAKE

REG. 21.08.2018

MODEL

**IONIQ G2** 

18.03.2023

CHIANG/ CHINA

Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	FRONT BUMPER? - NN			\$481.10
	FRONT BUMPER BRACKET TOP RH ? XM		\$35.00	\$350.00
10	FRONT BUMPER CLIPS?		\$2.20	\$22.00
10	FRONT BUMPER MOULDING ?			\$368.50
	1 FRONT RADIATOR GRILLE GOV			\$1,409.10
	SUB TOTAL			\$2,630.70
	20.00%		281.82	\$526.14
	DISCOUNTED TOTAL		1127.28	\$2,104.56
	DISCOUNTED TOTAL			
	1 FRONT NUMBER PLATE ? X NN			\$55.00
	TIFKONT NOWIBER PLATE : NN	la se se	1	\$55.00
	Labour Charge			
	Panel Beating			\$600.00
	Spray Painting Charge			\$300.00
	Check Wiring			\$60.00
	Tuff kote			\$60.00
	TOTAL LABOUR			\$1,020.00
	ESTIMATE TOTAL		1427.28	\$3,179.56
			1477.28	
		20	213.45	
	This is an initial estimate based on a visual inspection of th	e above ve	hicle. The final repair qua	ntum will

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.