

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0258/2023/EQ
DATE : 10-Mar-23
WIP : 11437

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian

4 days - ok - Johnr

19-Jun-23

OWNER'S NAME : DR ETHAN YI-PENG KOH
ADDRESS : 23 EAST SUSSEX LANE
SINGAPORE 279809

TELEPHONE : HP +65 97346692
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100477030-06
VEHICLE NO : **SLE 585 K**
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TF
MODEL YEAR : 27/7/2016
ENGINE NO : CZC 546610
CHASSIS NO : WAUZZZ8V2GA148296
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Mar-23
PLACE OF ACCIDENT : ALONG NEWTON CIRCUS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 585 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	
3	TO RENEW REAR WINDSCREEN.	S/N \$	480.00	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR RHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$ 500.00
TOTAL LABOUR CHARGES		: \$	4,640.00	\$ 780.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 585 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 780.00
7	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND RHS REAR FENDER.	\$	3,500.00	\$ 1,100.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	8,332.00	\$ 2,072.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 585 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1 \$	2,328.00 \$	1,862.40
2	REAR BUMPER FIXING PARTS	1 \$	213.00	
3	REAR BUMPER LOCKING MECHANISM - LH / RH	2 \$	34.00	
4	REAR BUMPER SPOILER	1 \$	279.00	
5	REAR BUMPER SIDE REINFORCEMENT	1 \$	680.00 \$	543.60
6	REAR BUMPER BRACKET - LH / RH	2 \$	32.00	
7	REAR BUMPER GUIDE SECTION - RH	1 \$	79.00	
8	REAR PARKING AID SENSOR - INNER / OUTER	2 \$	543.00 \$	212.00
9	REAR PARKING AID SEAL RING	4 \$	11.00	
10	REAR BUMPER WIRING SET	1 \$	578.00	
11	REAR OUTER TAIL LIGHT - RH	1 \$	1,030.00 \$	824.00
12	REAR INNER TAIL LIGHT - RH	1 \$	1,030.00 \$	824.00
13	REAR BUMPER REFLECTOR - RH	1 \$	49.00	
14	REAR LID	1 \$	3,373.00	
15	PACKING ADHESIVE	1 \$	22.00 \$	16.88
16	REAR LID ATTACHMENT PARTS	1 \$	326.00	
17	REAR LID FLAP GASKET	1 \$	242.00	
18	REAR LID LOCK	1 \$	196.00	
19	REAR LID FLAP LOCK COVER CAP	1 \$	9.00	
20	REAR LID LOCK STRIKER	1 \$	104.00	
SUB TOTAL SPARE PARTS		:	\$ 11,158.00	\$ 4,282.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 585 K
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		c/f	\$	4,282.88
21	REAR LID STOP BUFFER - LH / RH	2 \$	55.00	
22	AUDI EMBLEM	1 \$	152.00	\$ 121.60
23	"A3" INSCRIPTION	1 \$	110.00	\$ 87.60
	"TFSI" INSCRIPTION	1 \$	110.00	\$ 87.60
25	REAR SPOILER FIXING PARTS	1 \$	194.00	
26	REAR SPOILER FOAM STRIPS	1 \$	162.00	
27	REAR WINDOW	1 \$	961.00	
28	WINDOW PRIMER	1 \$	24.00	
29	REAR WHEEL HOUSING LINER	1 \$	281.00	
30	REAR WINDSCREEN SEALANT	S/N \$	200.00	
31	SUNDRIES	\$	400.00	
TOTAL SPARE PARTS		: \$	13,807.00	\$ 4,579.68
TOTAL LABOUR CHARGES		: \$	8,332.00	\$ 2,072.00
GRAND TOTAL		: \$	22,139.00	\$ 6,651.68

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-30/05/23

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT